OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT Tillamook County Surveyor's Office

SECTION: The Northwest	TOWNSHIP 1 North, 2 North	RANGE 7 West		
corner of Section 4, T1N, R7W				
COUNTY: Tillamook	And the state of t	B	Ī	DATE: 06-04-08
Name - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -	e Section corner common to T2N, R7	7W.	1	(Please check one)
Sections 32 and 33; T1N, R7W, Sections 4 and 5, W.M., Tillamook			図	Condition Report Only
County, Oregon.				Restoration
				Rewitness
				Unrecorded
				Reset at surface
Previous Rewitnesses, Restorations and Surveys, etc.: Rewitness Book 2, Page 284, Rewitness Book 2, Page 66b, Rewitness Book 7, Page 316, Survey map B-337, Tillamook County Survey Records.				
Found Monument(s) and Accessories (Condition & Source): Found a 3" diameter Oregon State Board of Forestry cap				
upright and in good condition. I placed a 12" diameter plastic cylinder and 120 pounds of concrete around the found				
monument. The cap is stamped as shown hereon. Found a 14" (Rewitness Bk. 7, Pg. 316 = 11") diameter Alder tree with				
bark scribing and tack visible at record position. Found a 34" diameter Douglas Fir tree (Rewitness Bk. 7, Pg. 316 = 28")				
with healed face at record location. Found a 29" diameter Douglas Fir tree (Bk. 7, Pg. 316 = 25") with healed face at record				
location. Found a rotting 48" diameter Douglas Fir stump (Rewitness Bk. 2, Pg. 284) with yellow metal location tag at				
record position. Found a broken and rotten 4" x 4" x 48" white painted cedar post with yellow metal location tag and placed it next to the corner monument. Also found an orange carsonite post (Rewitness Bk. 7, Pg. 316) at record position.				
	. Also found an orange carsonite pos and Description: Not applicable.			ch of Found Monument:
monument set (Procedures a	ind bescription. Not applicable.	اح	NGU	or or other monamone.
		l		T2N R7W
				LS 1998-2000
				\
\ S4 \ S5 \ \				
T1N				
				1951 199
New accessories set: Set a 72" hat section post 3 feet North of corner monument.				
New Positing Trans. No new basing trace were got				
New Bearing Trees: No new bearing trees were set.				
Location & Comments: This corner is located approximately 55' South of Diamond Mill Road.				
			<u>ـــــــ</u>	SURVEYOR'S SEAL
Firm / Agency Address: TILLAMOOK COUN	ITY SURVEYOR'S OFFICE		3	DURVETUR 3 SEAL
Address. HELANIOUR COUR	III GURAETOK G OFFICE			
Party Chief: Joe Jensen, PLS	60067, Survey Supervisor			
larty officer too defisers, i Lo	occi, ourte, eaperries			
Notes:				REGISTERED
			1	PROFESSIONAL
Mildwarener Danner D. Mahlett	DI S 40220 Tillomosk County	:		LAND SURVEYOR
Witnesses: Danny R. McNutt, PLS 49230, Tillamook County Surveyor.			$\overline{\sim}$	The state of the s
Surveyor.		d	D	anny R. mc Nutt
		i		OREGON
			I _	JULY 11, 2000
			ľr	PANNY R. MCNUTT
•	or completeness,		-	49230
V.	COV			RENEWAL12-31- 200 8



442