OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT Tillamook County Surveyor's Office

SECTION: 1,2,11 and 12	TOWNSHIP 2 South	RANG	NGE 10 West	
COUNTY: Tillamook			DATE: 11-18-08	
CORNER DESIGNATION: Th	e Section Corner common to Section	ns	(Please check one)	
1,2,11 and 12.			☐ Condition Report Only	
	4		□ Restoration	
			Rewitness	
	,		☐ Unrecorded	
			☐ Reset at surface	
<u></u>			□ Referenced Out	
Previous Rewitnesses, Resto Bearing Trees by RS 401 in E		g. 2, 2S	10W 1857, Section comer set from original	
protruding 0.4 Feet above grou (G.L.O.) – Found Rotted Stubs (Bk. 1, Pg. 422) – Found 4' tall (Bk. 1, Pg. 422) – Found 5' tall (Bk. 1, Pg. 422) – Found 6' tall	ind. Rotated Cap North. The monun	nent is st 53° W 41 73° W 26 60° E 11	1.0 Feet. 6.6 Feet. 11.2 Feet.	
Monument Set (Procedures a	and Description): Not applicable.		Sketch of Found Monument:	
			SZ S1 S12 S11 S12 S10 S11 S12 S10 S11 S12 S10 S1	
	diameter plastic cylinder around co		on tag North 4.0 feet from corner position. I new bearing trees have a nail and washer	
19" diameter Hemlock bears N 15" diameter Hemlock bears S	44° W 43.1 Feet, Scribed "T2S R10 52° E 9.50 Feet, Scribed "T2S R10 52° E 12.2 Feet, Scribed "T2S R10 87° W 10.5 Feet, Scribed "T2S R10	W S1 B W S12 E	BT", Tagged and Painted. BT", Tagged and Painted.	
Location & Comments:	MANAMENTALISE (A 1944) A 1944 A 1	den de la companione de		
Firm / Agency Address: TILLAMOOK COUN 201 Laurel Avenue Tillamook, Oregon			SURVEYOR'S SEAL	
Party Chief: Joe Jensen, P.L.S Notes:	S. 60067, Survey Supervisor		PROFESSIONAL LAND SURVEYOR	
Witnesses: Danny R. McNutt, Michael R. Rice, L.S.I. 16723,	P.L.S. 49230, Tillamook County Su Survey Technician	rveyor.	DANNY R. MCNUTT 49230 RENEWALI2 - 31- 2008	

