OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT Tillamook County Surveyor's Office

SECTION: East 1/4 corner of Section 34				West
COUNTY: Tillamook			DATE: 12-31-08	
and the control of the state of	e Quarter Corner common to Section	ons 34	1	(Please check one)
and 35.				Condition Report Only
				Restoration
			(2)	Rewitness
				Unrecorded
				Reset
				Referenced Out
4, Page 33 (W.E. Anderson); R 423, A-500, A-831, A-1704, A-5 Found Monument(s) and Acc monument is stamped as show control. Oregon North Zone Sta 7333216.7370. (Book 4, Page 67) – Found dov Highway 131. (Book 4, Page 67) – Found 35" Netarts-Oceanside Highway 13 (Rewitness #336) – Found hat () Indicates record information	tewitness Book 4, Page 67 (W.E. A 5710, A-6576, B-187, B-816, all local tessories (Condition & Source): Fin hereon. Tied the monument converte Plane in NAD 83/91 coordinate wined, rotten stump, bears S 10°30' (was 20") multi-topped Hemlock be 31.	inderson); I ated in Tilli Found 3" browentionally for the more W 69.5' or ears N 81°	Rewards with numer the	s cap in good condition, in cement. The n a total station using GPS established nent is N = 665401.9809, E =
				1/4 S34 S35 RS 287 1975
marked, "Terry Jones PLS 250 Used for occupy point to tie the said point is N = 665367.6640, backsight point, said point is 13 of the intersection of said Hwy. coordinate of N = 665483.819, 232°17'15" with a horizontal dis Y.P.C. indicates "Yellow Plastic New Bearing Trees: * 17" diameter Hemlock bears and painted. * 11" diameter Hemlock bears and painted. All new Bearing Trees have a mand T. All new bearings to Bear yellow Tillamook County Corne	7", 9.6' North of Power Pole #34844 one-quarter monument. The Oregon E = 7333268.997. Set a 5/8" Iron R 3' south of the southerly edge of part 131 and Deer Creek Road, said postance of 62.52'. Cap" N 74° E 121.4', on the north side of S 73° E 128.6', on the south side of mail and aluminum washer marked, ring Trees are grid bearings per NA	00 and 7.6 on North Z Rod with a vernent of soint has an ally tied and said HWY "Till. Co. S AD 83/91 O	' So cone Y.P. said Ore gle (Found a 5/8" Iron Rod with a Y.P.C. buth of southerly fog line of said Hwy. 131. State Plane NAD 83/91 coordinate for .C. marked, "Till. Co. Random", as a lid Hwy. 131 and approximately 30' easterly egon North Zone State Plane NAD 83/91 right from said setup to monument is
said Hwy. 131 in the highway c				SURVEYOR'S SEAL
Address: TILLAMOOK COUN	TY SURVEYOR'S OFFICE			JOHN E. ON O GENE
Party Chief: Joe Jensen, PLS	60067, Survey Supervisor	and is set a feet and a set a se		REGISTERED PROFESSIONAL LAND SURVEYOR
Notes:		1	,	/ www.
	and the second			Speph V. Gensen

G:\completed restorations\T1SR10WS34-35.doc