OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT Tillamook County Surveyor's Office

SECTION: 33 and 34	TOWNSHIP 1 South	RANG	E 10) West
COUNTY: Tillamook			DATE: 2-09-09	
CORNER DESIGNATION: The Quarter Corner common to Section				(Please check one)
and Section 34.				Condition Report Only
				Restoration
			188	Rewitness
MILLIANDO				Unrecorded
				Reset at surface
		-		Referenced Out
Previous Rewitnesses, Restorations and Surveys, etc: BLM Field Notes Volume: OR-R0337 Page 265 (GLO 1S10 Pg. 72) (1890), Book 1 Page 98 same as Book 4 Page 92 (1953), A-1203 (1964), Book 6 Page 157 (1965), A-1851 (1969), Book 5 Page 63 (1970), Rewitness #334 (1977), Tillamook County Survey Records.				
Found Monument(s) and Accessories (Condition & Source): Found a 3" brass cap in cement. The monument is stamped as shown hereon. Found a hat section post with tag 1.5' east of monument. Found 2 white cedar posts lying near the monument. (Book 6, Page 157) – Found 34" (was 24") Hemlock Stump, 7' tall, bears (N 69° 30' W 10.3'), scribing partially visible, tag. (Book 6, Page 157) – Found 28" (was 14") Hemlock Stump, 7' tall, bears (S 14° 30' E 21.4'), scribing "S34BT" visible, tag. () Indicates record information from Rewitness Book 6, Page 157, Tillamook County Survey Records.				
Monument Set (Procedures and Description): Not applicable. Sketch of Found Monument:				
			1/4 S33 S34 RS 287 1977	
New accessories set: Not applicable.				
New Bearing Trees set: *6" diameter Fir bears N 27° W 10.1', scribed "1/4 S33 BT", tagged and painted. *9" diameter Fir bears N 36° E 8.5', scribed "T1S R10W 1/4 S34 BT", tagged and painted. Attached found white BT tag. *10" diameter Fir bears S 32° E 18.1', scribed "T1S R10W 1/4 S34 BT", tagged and painted. *9" diameter Hemlock bears S 50° W 6.6', scribed "T1S R10W 1/4 S33 BT", tagged and painted. * Indicates yellow metal location tag affixed to new bearing tree. All new bearing trees have a nail and aluminum washer marked, "Till. Co. Surveyor", in face of blaze, between the scribed B and T. Location & Comments: Corner is located approx. 200' East of a				
North/South running logging ro	• •	والمراجعة		
Firm / Agency Address: TiLLAMOOK COUNTY SURVEYOR'S OFFICE 201 Laurel Avenue Tillamook, Oregon 97141				REGISTERED PROFESSIONAL
Party Chief: Joe Jensen, P.L.S. 60067, Survey Supervisor Notes:				Jaseph V. Jewsen OREGON JANUARY 10, 2006
Witnesses: Danny R. McNutt, P.L.S. 49230, Tillamook County Surveyor. Michael R. Rice, L.S.I. 16723, Survey Technician				JOSEPH V. JENSEN 60967 RENEWAL DATE: 08-30- 09

MAR 5 2005