## OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT Tillamook County Surveyor's Office

SECTION: SW Corner of 4	TOWNSHIP 3 South	RANGE 10 West		
COUNTY: Tillamook		DATE: 3-10-09		
CORNER DESIGNATION: The Section Corner Common to Sections 4,			!	(Please check one)
and 9, T. 3 S., R. 10 W., W.M.	South Sollier Sollimen to Southern 1	' -, -	×	Condition Report Only
Comments of the control of the contr				Restoration
				Rewitness
				Unrecorded
				Reset at surface
				Referenced Out
		otos Vo		: OR-R0337 Page 316 - 317 (GLO 3S10 Pg.
58) (1890), Book 3 Page 204 (1933 (1999), Tillamook County Survey Found Monument(s) and Access	3), Book 1 Page 506 (1962), Book 3 l Records. <b>Sories (Condition &amp; Source)</b> : Found	Page 17	1 (19 bra	ss cap up 0.4'. The monument is stamped as
shown hereon. Tied the monument directly using GPS established control. The Oregon North Zone State Plane in NAD 83/9' coordinate for the monument is N = 625922.780, E = 7321781.978 US Survey Feet. Found 1° Iron Pipe lying beside monume Found a 6' tall, 4" X 4" white post marked, "S4 – S9" on corresponding sides, bears S 22° E 1.5' from monument. Found a carsonite "Survey Marker" paddleboard bears North 2.0' from monument.  (G.L.O.) – Did not find the (12" dia. Hemlock bearing N 87° E 12 lks.).  (G.L.O.) – Did not find the (12" dia. Hemlock bearing N 25° W 26 lks.).  (G.L.O.) – Found 24" dia. (was 12"), Fir Stump, 7' tall, bears S 72° W 7.3' (S 82° W 11 lks.), scribing partially visible.  (Book 3, Page 171) – Did not find the (22" dia. Fir bearing N 19° E 13 lks.).  (Book 3, Page 171) – Did not find the (19" dia. Cedar Stump, 4' tall, bears (S 9°30' E 21 lks.), scribing partially visible, U.S.F.S. tag.  (Book 3, Page 171) – Did not find the (19" dia. Hemlock bearing N 29° W 26 lks.).  (Map B-1226 A&B) – Found 12" dia. (was 8"), Alder Stump, 7' tall, bears (N 55° E 3.2'), scribing visible, tag.  (Map B-1226 A&B) – Found 14" dia. (was 8"), Hemlock Stump, 10' tall, bears (N 86° W 8.7'), healed scar and tag.  (Map B-1226 A&B) – Found 16" dia. (was 8"), Hemlock Stump, 10' tall, bears (S 30° E 13.6'), axe work visible.  () Indicates record information, Tillamook County Survey Records.  Monument Set (Procedures and Description): Not applicable.  Sketch of Found Monument:				Found 1" Iron Pipe lying beside monument. S 22° E 1.5' from monument. Found a  11 lks.), scribing partially visible.  12'), scribing visible, tag.  2'), scribing visible, tag.  2'W 8.7'), healed scar and tag.  3'W 6.7'), healed scar and tag.  4 W 6.7'), axe work visible.  13.6'), axe work visible.  13.6'), axe work visible.
L5 1084 1986 1986 19 DISTRICTION DISTRICTI				L5 1084 1986 1986 TO DISTRIB
New accessories set: Set 120 lbs. of concrete in a 12" diameter cylinder around monument. Set a 72" hat section post with a yellow metal location tag affixed, South 2.8' from monument.				
New Bearing Trees set: No bearing trees available.				
Location & Comments: Corner i logging road on the top of a ridge	s located approx. 30' North of a grav bearing NW and SE from monument.	el		
Firm / Agency Address: TILLAMOOK COUNTY SURVEYOR'S OFFICE 201 Laurel Avenue Tillamook, Oregon 97141				SURVEYOR'S SEAL
Party Chief: Joe Jensen, P.L.S. 60067, Survey Supervisor  Notes:				REGISTERED PROFESSIONAL LAND SURVEYOR  Jaseph V. Jeusen
Witnesses: Danny R. McNutt, P.L.S. 49230, Tillamook County Surveyor Michael R. Rice, L.S.I. 16723, Survey Technician				JANUARY 10, 2006 JOSEPH V. JENSEN 60067 RENEWAL DATE: 06-30- 09

G:\completed restorations\T3SR10WSec4,5,8,9.doc

BOOK 7 · 488