## OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT Tillamook County Surveyor's Office

SECTION: South 1/4 of 4	TOWNSHIP 3 South	RANGE 10 West		
COUNTY: Tillamook	A CONTRACTOR OF THE PROPERTY O	<u></u>		DATE: 5-01-09
	e Quarter Corner common to Sections	4 and		(Please check one)
9, T. 3 S., R. 10 W., W.M.				Condition Report Only
				Restoration
			(2)	Rewitness
				Unrecorded
				Reset at surface
				Referenced Out
59 (1890); Resurvey BLM Field Rewitness Card #589 (1971) (1 Tillamook County Survey Reco	Notes Volume: OR-R0545 Page:134 976); Rewitness Book 6, Page 409 (1 rds.	(1933) s 989); <b>M</b> a	ame ip B	-1680 (1993); Map B-2267 (1999);
Found Monument(s) and Accessories (Condition & Source): Found a 2-1/2" G.L.O. Brass Cap up 1.0', in good condition The monument is stamped as shown hereon. Tied the monument directly using GPS established control. The Oregon North Zone State Plane in NAD 83/91 grid coordinate for the monument is N = 625766.577, E = 7324382.629, U.S. Feet. Found Steel Post lying down, reset East 3.0' from monument.  (G.L.O.) – Found 26" dia. (was 25") badly rotten Hemlock Stub, 5' tall, bears (N 22° W 15 lks.), axe marks visible, CZ tag. (G.L.O.) – Found (15" dia.) rotten Hemlock stub, 6' tall, bears (S 69° W 14 lks.), axe marks visible.  (Rewitness Card #589 1976) – Found 31" (was 18") dia. Hemlock, bears N 16° W 15.7' (N 18° W 12.6'), healed face and tag (Rewitness Book 6, Page 409) – Found 12" (was 6") dia. Hemlock Stump, 1' tall, bears S 65° E (S 65° W) (15.25'), scribing part. visible.				
( ) Indicates record information from Tillamook County Survey Records.  Monument Set (Procedures and Description): Not applicable.  Sketch of Found Monument:				
New accessories set: Set 120 lbs, of concrete in a 12" diameter cylinder around menument. Scribed a "PT" on the				
New accessories set: Set 120 lbs. of concrete in a 12" diameter cylinder around monument. Scribed a "BT" on the 31" Hemlock bearing tree which bears N 16° W 15.7'.				
				1/4 S4 BT", tagged and painted. or" in the face of the blaze between the
Location & Comments: The corner located on top of, and at the most westerly end of, an East-West running ridge approximately 1000 feet South of an existing logging road.				
Firm / Agency Address: TILLAMOOK COUNTY SURVEYOR'S OFFICE 201 Laurel Avenue Tiliamook, Oregon 97141				SURVEYOR'S SEAL  REGISTERED
Party Chief: Joe Jensen, P.L.S. 60067, Survey Supervisor				PROFESSIONAL LAND SURVEYOR
Notes:				Gaseph V. Gensen
Witnesses: Danny R. McNutt, P.L.S. 49230, Tillamook County Surveyor. Michael R. Rice, L.S.I. 16723, Survey Technician				OREGON JANUARY 10, 2008 JOSEPH V. JENSEN 60067
				RENEWAL DATE: 06-30-2011

