OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT Tillamook County Surveyor's Office

SECTION: SW Cor. 29	TOWNSHIP 3 North	RANGE	ANGE 7 West		
COUNTY: Tillamook	I			DATE: 5-05-09	
CORNER DESIGNATION: The	Section Corner common to 29, 30, 3	1 and	H	(Please check one)	
32.	, ,	↓		Condition Report Only	
				Restoration	
			図	Rewitness	
				Unrecorded	
				Reset at surface	
				Referenced Out	
Previous Rewitnesses, Restorations and Surveys, etc: BLM Field Notes Volume: OR-R0353 Page 633 (GLO 3N7 Page 60) (1891), Book 2 Page 154 (1952), Tillamook County Survey Records.					
Found Monument(s) and Accessories (Condition & Source): Found a 3" U.S.F.S. brass cap in good condition, up 0.5'. The monument is stamped as shown hereon. Found a white cedar post with a yellow metal location tag, lying down on the east side of the monument.					
(G.L.O.) – Did not find the (20" X 14" X 12" basalt stone) marked with 1 notch on the South and 5 notches on East sides. (G.L.O.) – Did not find the (12" Hemlock bearing N 58° E 30 lks.). (G.L.O.) – Found 3' tall pile of rotten remains (was 17" Hemlock) bearing (S 47° E 33 lks.).					
(G.L.O.) – Did not find the (16" Hemlock bearing S 24° W 68 lks.). (G.L.O.) – Did not find the (14" Hemlock bearing N 42° W 22 lks.).					
(Book 2, Page 154) – Found (48" dia. Fir Stump, 4' tall, bearing N 0°30' W 9.7', scribed "S30 BT") with a bearing tree tag. (Book 2, Page 154) – Found (56" dia. Fir Stump, 6' tall, bearing S 88° W 24.9'), no scribing visible, rotten face. (Book 2, Page 154) – Found (36" dia. Fir Stub, 10' tall, bearing S 58°30' E 41.8', scribed "T3N R7W S32 BT RE 2311"), tag. (Book 2, Page 154) – Found (63" dia. Fir Stump, 5' tall, bearing N 71° E 26.7', scribed "T3N R7W S29 BT"), with tag.					
(Book 2, Page 154) – Did not find the (29" Hemlock Stub, bearing S 47° E 21.5', with a metal location poster). () Indicates record information from Tillamook County Survey Records.					
Monument Set (Procedures and			f Fo	ound Monument:	
(•		
			_	ATE BOARD OF	
			131	7 T3N R7W (3)	
		1	(3)	830 839 100 100 100 100 100 100 100 100 100 10	
(8) 530 529 \\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\				W	
		/	1	S31 S32	
			//	1952	
			\	1952	
				2311	
New accessories set: Set 120 lbs. of concrete in a 12" diameter cylinder around monument. Set a 72" hat section post 3.0'					
West of the monument.					
New Bearing Trees set: 23" dia. Hemlock bears, N 21° W 7.9', scribed, "T3N R7W S30 BT", tagged and painted.					
27" dia. Hemlock bears, N 76° E 18.2', scribed, "T3N R7W S29 BT", tagged and painted.					
				or", in face of blaze, between the scribed "B	
and T" as well as a yellow metal location tag affixed.					
	is located on a steep slope approx.	250'			
North of Northside Logging Road	•	I			
Firm / Agency	and the second s			SURVEYOR'S SEAL	
Address: TILLAMOOK COUNT	Y SURVEYOR'S OFFICE			REGISTERED	
201 Laurel Avenue		ļ		PROFESSIONAL	
Tillamook, Oregon 9	7141	1		LAND SURVEYOR	
Party Chief: Joe Jensen, P.L.S.	60067, Survey Supervisor			Jaseph V. Gensen	
				OREGON	
Notes:				JANUARY 10, 2008 JOSEPH V. JENSEN 60067	
Witnesses Danny D. Mahlutt D.	L C 40220 Tillomank County C			RENEWAL DATE: 06-30- 20 11	
	L.S. 49230, Tillamook County Surve .l. 16723, Survey Technician	yor.		•	
The second state of the second				AMOOK COLL	

ML 20 2009