OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT Tillamook County Surveyor's Office

SECTION: SW Corner of 26	TOWNSHIP 2 South	RANGE 9	RANGE 9 West	
COUNTY: Tillamook DATE: 5-15-09				
CORNER DESIGNATION: The Southwest Corner of Section 26 and the			(Please check one)	
Northwest Corner of Section 35 only.		192	Condition Report Only	
	•	D	Restoration	
			Rewitness	
			Unrecorded	
			Reset at surface	
		10	Referenced Out	
(1857), GLO Re-survey in BLM Field Notes GLO Re-survey in BLM Field Notes Tillamook County Survey Records. Found Monument(s) and Access is stamped as shown hereon. Tied NAD 83/91 coordinate for the moni (GLO 1884) — Did not find the (18" (GLO 1884) — Did not find the (15" (GLO 1956) — Found 2 1/2" GLO B cylinder and 120 pounds of concre N34° 10'48"E 48.79'.	eld Notes Volume: OR-R0309 Page 98 Volume: OR-R0567 Page 98 (1956) Fories (Condition & Source): Found the monument directly using GPS elument is N = 634432.515, E = 73635 dia. Hemlock bearing S 64°30′ E 17 dia. Hemlock bearing N 67°30′ E 86 grass Cap marked, "T2S R9W S26 R te (N34°E 49.1′ Rewitness Card #40	154 (GLO 2Si), Map B-40 I a 3" GLO Bestablished or 189,324 US 5 lks.). Iks.). M 1956", in 18), tied with	mound of stone and a 12" diameter plastic GPS and now at grid bearing and distance	
(GLO 1956) – Found 2 1/2" GLO Brass Cap marked, "T2S R9W S35 RM 1956", in a mound of stone and a 12" diameter plastic cylinder and 120 pounds of concrete (S74°E 26.29' Rewitness Card #408), tied with GPS and now at grid bearing and distance S74° 36'24"E 25.97'. (GLO 1956) – Found 2 1/2" GLO Brass Cap marked, "T2S R9W S27 S34 S26 1956", in a mound of stone and a 12" diameter plastic cylinder and 120 pounds of concrete (N0° 23' 43" E 246.2' Map B-404), tied with GPS and now at grid bearing and distance N02° 42'58"E 246.31'. () Indicates record information, Tillamook County Survey Records.				
Monument Set (Procedures and	Description): Not applicable.	Sketch of F	ound Monument:	
			1956	
New pagagaring gat. Cat punch	mark on cap, set a hat section post	with a vallou	v metal location poster bearing S 8° E 1.35'	
from monument.	mark on cap, set a nat section post	with a yellow	Metal location poster bearing 0 0 E 1.35	
New Bearing Trees set: No bearing trees available.				
Location & Comments: Corner is gravel logging road #M600.	s located at the west edge of a dead-	-end		
Firm / Agency Address: TILLAMOOK COUNTY SURVEYOR'S OFFICE 201 Laurel Avenue Tillamook, Oregon 97141			SURVEYOR'S SEAL REGISTERED	
Party Chief: Joe Jensen, P.L.S. 60067, Survey Supervisor		- and the same and	PROFESSIONAL LAND SURVEYOR	
Notes:			Gaseph V. Geusen OREGON JANUARY 10, 2006	
	.S. 49230, Tillamook County Survey . 16723, Survey Technician	or	JOSEPH V. JENSEN 60067 RENEWAL DATE: 06-30- 2011	