OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT Tillamook County Surveyor's Office

SECTION: 30	TOWNSHIP 2 South	RANGE 8 West		
COUNTY: Tillamook		<u> </u>	DATE: 7-01-09	
CORNER DESIGNATION: The West Quarter of Section 30 only.			i	(Please check one)
CORNER DESIGNATION. THE V	est Quarter or occurred only.			Condition Report Only
			_	Restoration
		<u> </u>	Œ	Rewitness
		<u> </u>		Unrecorded
		<u> </u>		Reset at surface
		<u> </u>	_	Referenced Out
Previous Rewitnesses, Restorations and Surveys, etc: BLM Field Notes Volume: OR-R0267 Page 202 (GLO 2S8 Page 64) (1883), Rewitness Book 1 Page 366 (1959), Map A-1094 (1963), Map B-758 (1977), Tillamook County Survey Records.				
Found Monument(s) and Accessories (Condition & Source): Found a 3" O.S.B.F. Brass Cap with a rock collar, set in				
Rewitness Book 1, Page 366. The monument is stamped as shown hereon. Tied the monument conventionally using GPS established control. The Oregon North Zone State Plane in NAD 83/91 grid coordinate for the monument is N = 636229.066, E = 7374013.543, US Survey Feet. (G.L.O.) – Found original (14" X 10" X 4" Basalt Stone marked 1/4) in rock collar. (G.L.O.) – Found 20" dia. (was 6" Spruce) rotted Hemlock stump bearing (N 60° E 11 lks. [7.26']) axe work visible.				
(G.L.O.) – Found 20° dia. (was 6° Spruce) folled Hermock stump bearing (N 60° E 11 lks. [7.20]) axe work visible. (G.L.O.) – Found 28° dia. (was 7° Spruce) Hemlock stump, 2' tall, bearing (S 62° W 31 lks. [20.46'].				
(G.E.O.) – Found 28° dia. (was 7° Spruce) Herniock stump, 2° tah, bearing (3° 62° W 3° 188. [20.46]. (Book 1, Page 366) – Found uproot (was 19" dia. Hemlock) bearing (N 82° E 13.0').				
(Book 1, Page 366) – Found (4" X 4" cedar post), burnt badly, with tag, lying next to monument.				
(Book 1, Page 366) – Found (4 X4 Cedal post), burne starty, with tag, tying flox to this family. (Book 1, Page 366) – Found (rock bluff 10' high, 25' long bears S.E. 24').				
() Indicates record information, Tillamook County Survey Records.				
[] Indicates converted value from				
Monument Set (Procedures and	Description): Not applicable.	Sketch of	f F	ound Monument:
New accessories set: Set a nail with center punch on rock bluff for an occupy point Zone State Plane in NAD 83/91 grid coordinate is N = 636207.747, E = 7374039.828 with a red plastic cap marked, "Till. Co. Random" on logging road for a backsight point Zone State Plane in NAD 83/91 grid coordinate is N = 636140.120, E = 7374063.524 in a 12" diameter cylinder around monument. Re-stacked the rock collar. Reset the computation of the control of the contro			nt to tie the monument. The Oregon North 8, U.S. Survey Feet. Set a 5/8" X 40" iron rod int to tie the monument. The Oregon North 4, U.S. Survey Feet. Set 120 lbs. of concrete original stone on the westerly side of	
New Bearing Trees set:				
8" dia. Fir bears N 54° E 7.5', scribed "1/4 S30 BT", with a yellow metal location tag and an aluminum nail with washer marked "Till. Co. Surveyor" on the face. 8" dia. Fir bears S 50° E 14.5', scribed "T2S R8W BT", with a yellow metal location tag and an aluminum nail with washer marked "Till. Co. Surveyor" on the face.				
	s located approx. 100' North of a gra	vel		
logging road, approx. 30' N.W. of a				
Firm / Agency				SURVEYOR'S SEAL
Address: TILLAMOOK COUNTY SURVEYOR'S OFFICE				
201 Laurel Avenue				REGISTERED
Tillamook, Oregon 97141				PROFESSIONAL
Party Chief: Joe Jensen, P.L.S. 60067, Survey Supervisor				LAND SURVEYOR
Nata Dividali	the of the meaning of the evident of	000		Gaseph V. Gensen
Notes: Digital images were taken of the monument, the original stone, and the new bearing trees.				OREGON JANUARY 10, 2008
Witnesses: Danny P McNutt D	L.S. 49230, Tillamook County Surve	vor		JOSEPH V. JENSEN
	.l. 16723, Survey Technician	,0,		60067 RENEWAL DATE: 06-30- 2011



BOOK