## OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT Tillamook County Surveyor's Office

SECTION: 4	TOWNSHIP 1 South	RANGE	RANGE 7 West	
COUNTY: Tillamook		1		DATE: 6-22-09
	osing Corner common to Section 4 a	and		(Please check one)
Section 5.		ŀ		Condition Report Only
		Ī		Restoration
			×	Rewitness
				Unrecorded
				Reset at surface
		Ī		Referenced Out
Previous Rewitnesses, Restorations and Surveys, etc: BLM Field Notes Volume: OR-R0053 Page 5 (Original 1856), BLM Field Notes Volume: OR-R0345 Page 155-156 (GLO Re-Survey 1S7 Pages 68-69) (1891), Rewitness Book 2 Page 167 (1952), Rewitness Book 6, Page 320 (1987), Tillamook County Survey Records.				
Found Monument(s) and Accessories (Condition & Source): Found a 3" O.S.B.F. Brass Cap, up 0.8', leaning slightly, in good condition. The monument is stamped as shown hereon. Found carsonite post lying next to the monument.  (G.L.O. 1891) – Did not find the (14" Hemlock bears N 70 1/2° W 9 lks. [5.94']).  (G.L.O. 1891) – Found 52" (was 50") rotten Hemlock stump, bears (S 22° W 58 lks. [38.28']), no scribing visible.  (G.L.O. 1891) – Did not find the (12" Hemlock bears S 10° E 106 lks. [69.96']).  (Book 2, Page 167) – Found (63" Fir Stump bears S 13 1/2° E 71.3'), rotten with no scribing visible.  (Book 2, Page 167) – Found (84" Fir Stump bears S 63° W 118.8'), rotten, hollow, with no scribing visible.  (Book 6, Page 320) – Found 24" (was 10") Fir, bears (S 57° W 68.1') healed face.  (Book 6, Page 320) – Found 7" Fir Stub bears (S 42° E 34.0'), 3' tall, scribing partially visible.  ( Indicates record information, Tillamook County Survey Records.				
Monument Set (Procedures and		Sketch o	of F	ound Monument:
TIN R7W ST				T1N R7W 88 T1S R7W 88
<b>New accessories set:</b> Set 120 lbs. of concrete in a 12" diameter cylinder around monument. Reset found carsonite post West 2.0' from monument. Set a 72" hat section post with tag, 3.0 South of monument. Re-scribed the found 24" bearing tree at S 57° W with a new distance of 67.1' to the face, added a nail and washer marked, Till. Co. Surveyor between the scribed "B" and "T".				
New Bearing Trees set: 21" dia. Fir bears N 73° W 12.1', scribed "T1N R7W CC BT", with a yellow metal location tag and an aluminum nail with washer marked "Till. Co. Surveyor" on the face. 22" dia. Fir bears N 33° E 9.6', scribed "T1N R7W CC BT", with a yellow metal location tag and an aluminum nail with washer marked "Till. Co. Surveyor" on the face.				
Location & Comments:				
Firm / Agency Address: TILLAMOOK COUNTY SURVEYOR'S OFFICE 201 Laurel Avenue Tillamook, Oregon 97141				SURVEYOR'S SEAL
Party Chief: Joe Jensen, P.L.S. 60067, Survey Supervisor				REGISTERED PROFESSIONAL LAND SURVEYOR
<b>Notes:</b> Digital images were taken of the monument, the found bearing trees, and the new bearing trees.				Joseph V. Jeusen
Witnesses: Danny R. McNutt, P.L.S. 49230, Tillamook County Surveyor Michael R. Rice, L.S.I. 16723, Survey Technician				OREGON JANUARY 10, 2008 JOSEPH V. JENSEN 60067



RENEWAL DATE: 06-30-2011