OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT Tillamook County Surveyor's Office

SECTION: Section 3	TOWNSHIP 2 South	RANG	RANGE 7 West	
COUNTY: Tillamook			DATE: 10-7-09	
CORNER DESIGNATION: The Quarter Corner common to Sections 3 and 4,				(Please check one)
T. 2 S. R. 7 W.				Condition Report Only
				Restoration
			×	Rewitness
				Unrecorded
				Reset at surface
				Referenced Out
Previous Rewitnesses, Restorations and Surveys, etc: BLM Field Notes Volume: OR-R0345 Page 288, (GLO Book 2S7				
Page 33) (1891), Tillamook County Survey Records; Rewitness Book 2, Page 83 (1951), Rewitness Book 6, Page 381 (1988), Tillamook County Survey Records.				
Found Monument(s) and Accessories (Condition & Source): Found a 3" O.S.B.F. Brass Cap, good condition, protruding 1.0',				
with a rock collar. The monument was set in Rewitness Book 2, Page 83 (1951). The monument is stamped as shown hereon.				
The original post is missing.				
(G.L.O.) – Did not find the (5" Vine Maple bears S 27° W 44 lks. [29.04']).				
(G.L.O.) – Did not find the (18" Hemlock bears S 59 1/2° E 58 lks. [38.28']). (Book 2, Page 83) – Found (36" Fir Snag), badly rotten, (bears S 54° W 70.0'), scribing partially visible.				
(Book 2, Page 83) – Found (67" Fir Stump bears S 78 1/2° E 92.2′), with a yellow metal location tag and scribing partially visible.				
(Book 6, Page 381) – Found 13" dia. (was 10") D. Fir, bears (N 83° W 11.4'), healed scar and tag.				
(Book 6, Page 381) – Found 10" dia. (was 7") Fir Stub, 18" tall, bears (N 38° E 14.8'), scribing partially visible and yellow metal				
location tag on broken off tree lying east of stub.				
() Indicates record information, Tillamook County Survey Records. [] Indicates converted value from links to feet.				
			of Found Monument:	
				·
		E BOARD OF		
			1/4	
		$\binom{5}{6}$ S4 S3 $\binom{2}{7}$		
			\\	
		LS 1998-1988 1951		
		142		
•				
New accessories set: Set 120 lbs. of concrete in a 12" dia. cylinder around monument. Set 72" hat section post with a yellow				
metal location tag, 3.0' North from monument. Reset rock collar.				
New Bearing Trees set:				
*23" dia. Double Alder bears S 67° E 25.2', bark scribed "T2S R7W 1/4 S3 BT", tagged and painted.				
*11" dia. D. Fir bears S 12° W 6.1', scribed "T2S R7W S4 BT", tagged and painted.				
*Indicates an aluminum nail with washer marked, "Till. Co. Surveyor" in the face between the scribed "B" and "T" and a yellow				
metal location tag attached to the bearing tree.				
Location & Comments: Monument is located on a slope approximately 50' North of Bark Shanty Road and 75' South of a creek.				
	South of a creek.			
Firm / Agency Address: TILLAMOOK COUNTY S	SUBVEYOR'S OFFICE			SURVEYOR'S SEAL
201 Laurel Avenue				
Tillamook, Oregon 97141				REGISTERED
				PROFESSIONAL
Party Chief: Joe Jensen, P.L.S. 60067, Survey Supervisor				LAND SURVEYOR
Notes: Digital images were taken of the manuscraft the found heavily				Contraction of the Contraction o
Notes: Digital images were taken of the monument, the found bearing trees and the new accessories.				Gaseph V. Cleuren
ares and the new accessories.				OREGON
Witnesses: Danny R. McNutt, P.L.S. 49230, Tillamook County Surveyor				JANUARY 10, 2006
Michael R. Rice, L.S.I. 16723, Survey Technician				JOSEPH V. JENSEN
				60067 RENEWAL DATE: 06-30- 2011
	•			""" TETVAL DAIE: 08-30- 2011



 $G: \verb|\completed| restorations \verb|\T2SR7WQuarterSec3,4.doc| \\$

BOOK 7 545