OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT Tillamook County Surveyor's Office

SECTION: SW 10	TOWNSHIP 2 South	RANGE 7 West		
COUNTY: Tillamook			DATE: 10-01-09	
CORNER DESIGNATION: The Section Corner common to Sections 9, 10,			(Please check one)	
16, and 15, T. 2 S., R. 7 W., W.M.				Condition Report Only
·				Restoration
			<u></u>	Rewitness
		+		Unrecorded
		F		Reset at surface
				Referenced Out
Previous Rewitnesses, Restorations and Surveys, etc: BLM Field Notes Volume: OR-R0345 Pages 0280-0281; (GLO Book 2S7 Pages 28-29,1891), Tillamook County Survey Records; Rewitness Book 2, Page 87 (1951), Tillamook County Survey Records.				
Found Monument(s) and Accessories (Condition & Source): Found a 3" O.S.B.F. Brass Cap, in good condition, up 0.8', in a mound of stone. The monument was set in Rewitness Book 2, Page 87 (1951). The monument is stamped as shown hereon. The original post is missing. Found a 3' tall rotten Fir stump, was 48" diameter, no scribes visible, found at record position (N 33° W 96 links [63.36']). Found a 6' tall rotten Fir stump, was 66" diameter, scribes partly visible, found at record position (N 32° E 24 links [15.84']). Found a 6' tall rotten Fir stump with railroad spikes, was 44" diameter, scribes partly visible, found at record position (S 59° E 169 links [111.54']). Found a 4' tall rotten Fir stump with yellow metal tag, was 64" diameter, scribes partly visible, found at record position (S 03° W 24 links [15.84']). () Indicates record information, Tillamook County Survey Records.				
[] Indicates converted value from				
Monument Set (Procedures and I	Description): Not applicable.	Sketch o	f Fo	ound Monument:
				BOARD
			/	T2S R7W W
	ŀ			59 510 5
			12	S16 S15 C
			/	\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\
				1951
The state of the s				
New accessories set: Set 120 lbs. of concrete in a 12" dia. cylinder around monument. Set 72" hat section post with a yellow				
metal location tag, 3.0' South from monument.				
New Bearing Trees set:				
*23" dia. Douglas Fir bears S 33° W 10.5', scribed "T2S R7W S16 BT", tagged and painted.				
*22" dia. Douglas Fir bears N 57° W 34.1', scribed "T2S R7W S9 BT", tagged and painted.				
*13" dia. Douglas Fir bears N 84° E 40.5', scribed "T2S R7W S10 BT", tagged and painted. *11" dia. Douglas Fir bears S 47° E 48.8', scribed "T2S R7W S15 BT", tagged and painted.				
17 dia. Douglas Fill bears 0 47 E 40.0 , suitbed 123 NYW 313 BT , tagged and painted.				
*Indicates a yellow metal location tag affixed and a nail with an aluminum washer marked "Till. Co. Surveyor" between the scribed "B" and "T".				
Location & Comments:	The state of the s	ľ	***	
Firm / Agency	The second secon			SURVEYOR'S SEAL
Address: TILLAMOOK COUNTY S	SURVEYOR'S OFFICE			SURVETUR S SEAL
201 Laurel Avenue				
Tillamook, Oregon 971	41			REGISTERED
				PROFESSIONAL
Party Chief: Joe Jensen, P.L.S. 60067, Survey Supervisor				LAND SURVEYOR
Notes: Digital images were taken of the monument, the found bearing				1. 11 1/1/2
trees and the new accessories.	cor or the monument, the found bear	un g		Joseph V. Gewen
and the deceaseres.		i		OREGON
Witnesses: Danny R. McNutt, P.L		/or		JANUARY 10, 2006
	. 16723, Survey Technician			JOSEPH V. JENSEN 60067
				RENEWAL DATE: 08-30- 2011

