OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT Tillamook County Surveyor's Office

SECTION: SE COR 10	TOWNSHIP 2 North	RANGE 10 West			
COUNTY: Tillamook			DATE: 5- 05 -10		
CORNER DESIGNATION: The Section Corner common to Sections 10, 1				(Please check one)	
14 and 15, T. 2 N., R. 10 W., W.M.			Co	ondition Report Only	
				estoration	
Į			Re	witness	
			Un	recorded	
			Re	eset at surface	
			Re	eferenced Out	
Previous Rewitnesses, Restorations and Surveys, etc: BLM Field Notes Volume: OR-R0122 Page 125, (GLO Book 2N10					
Page 26) (1873), Map B-380 (1958), Tillamook County Surveyor Field Note Bin T2N R10W, Tillamook County Survey Records.					
Found Monument(s) and Accessories (Condition & Source): Found a nail inside a 1 1/2" Iron Pipe, leaning into a rotten stump, up 0.5'. No original evidence was found and the monument was proportioned on Map B-380 (1958). Found a Cedar Post with visible scribing and a yellow metal location tag, lying next to monument. The intent of this rewitness is to perpetuate the position of the proportioned corner on Map B-380 (1958). (Map B-380) – Found rotten Hemlock Stump, (was 4"), 2'tall, bears (N 76° 45' W 16.62') no visible marks. (Map B-380) – Found 26" Hemlock High Stump, (was 10"), 9' tall, bears (S 55° 45' W 46.71') no visible marks.					
(Map B-380) – Did not find the (10" Hemlock bears S 16° W 47.42'). (Map B-380) – Did not find the (3" Hemlock bears N 86° 45' E 22.92').					
() Indicates record information, Tillamook County Survey Records. Monument Set (Procedures and Description): We referenced the Sketch of Set Monument:					
monument using the nail inside the		Skelcii oi	Set IV	onument.	
record accessories. We then set a 3" diameter Tillamook County					
Brass Cap on a 30" long, 1 1/2" diameter Iron Pipe in its position and			6	COUNTY SUAL	
laid the found pipe next to the set monument. We then occupied the			TOW RIOW TO THE TOWN THE		
monument directly using GPS established control. The Oregon North Zone State Plane in NAD 83/91 grid coordinate for the position		[20 KIOW 33 32]			
is N = 746932.779, E = 7336888.343 U.S. Survey Feet.			S10 S11		
Convergence = -2°24'02.76822", Grid Scale = 0.99993218.		S15 S14			
				1	
			81	2010 3	
			\	2010 27 0/STURB \$500 FINE OR 310	
	<u>.</u>				
New accessories set: Set 120 lbs. of concrete in a 12" dia. cylinder around the monument. Set a rock collar around said 12"					
cylinder. Set 72" hat section post with a yellow metal location tag South 3.0' from the monument. Re-set the found Cedar Post					
with visible scribing and a yellow metal location tag, S 45° W from the set monument.					
New Bearing Trees set:					
No trees available to mark. Location & Comments: Monument is located approximately 40' South of					
		1 01			
Jetty Creek logging road and 50' North of Cross Over logging road, approximately 200' East of the junction of said roads.					
Firm / Agency				SURVEYOR'S SEAL	
Address: TILLAMOOK COUNTY SURVEYOR'S OFFICE					
201 Laurel Avenue					
Tillamook, Oregon 971	141	1		REGISTERED	
Party Chief: Joe Jensen, P.L.S. 60067, Survey Supervisor				PROFESSIONAL LAND SURVEYOR	
Party Ciner. See Jensen, F.E.S. 00007, Survey Supervisor			i	WHILE COLLEGE	
Notes: Digital images were taken of the monument and the new accessories.			,	Gaseph Gensen	
Witnesses: Danny R. McNutt, P.L.S. 49230, Tillamook County Surveyor				OREGON JANUARY 10, 2006	
Michael R. Rice, L.S.I. 16723, Survey Technician				JOSEPH V. JENSEN	
				RENEWAL DATE: 06-30-2011	

