## OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT Tillamook County Surveyor's Office

SECTION: South 1/4 of Section	TOWNSHIP 2 South	RANGE 7 West		
13				DATE: 6-1-10
COUNTY: Tillamook				(Please check one)
CORNER DESIGNATION: The Quarter Corner Common to Sections 13				Condition Report Only
24, T. 2 S., R. 7 W., W.M.		-	믐	Restoration
		}	떨	
		ŀ		Unrecorded
				Reset at surface
Previous Rewitnesses, Restorations and Surveys, etc: BLM Field Notes Volume: OR-R0345, Page 234-235, 1891; Tillamor County GLO Book 2S10, Pg. 7, 1891; Rewitness Book 1, Page 209,1955; Rewitness Book 7, Page 569,2010; Map B-2916, 2005; Map B-3063, 2006; Tillamook County Survey Records.				
Found Monument(s) and Accessories (Condition & Source): Found a 2-1/2" diameter aluminum cap stamped "LHL LBR CORP", flush in good condition with a rock collar surrounding monument. The monument is described in Rewitness Book 1, Page 209 (1955), Tillamook County Survey Records. The cap is stamped as shown hereon. Found a southerly leaning 3" x 3" cedar post South 2.5', of the monument (SW 2.0'). The distance to the monument was measured at the base of the post.  (G.L.O.) — Original post is missing. The original bearing trees are gone.  (Rewitness Book 1, Page 209) — Found a 46" diameter Fir stump with scribing visible found at record position. (46" Fir stump bears S 25° W 15.6').  (Rewitness Book 1, Page 209) — Found a 54" diameter Fir stump with scribing visible and a yellow metal location tag found at record position. (54" Fir stump bears N 53° E 40.2').  Found a 13" diameter Douglas Fir (was 11") which bears S 51° W 19.62' with a partially healed face with scribing visible at record position.  Found a 14" diameter Douglas Fir (was 13") which bears N 66° 30' E 29.71' with a healed face at record position.  Our field measurements were taken at the found nails set in the base and side center of the tree.  ( ) indicates record information from Rewitness Book 1, Page 209, Tillamook County Survey Records.				
Monument Set (Procedures and Description): N/A  Sketch of Found Monument:				
		13 		
New accessories set: Set 120 pounds of concrete in a 12" diameter cylinder and replaced the rock collar around the monument. Set a 72" hat section post with a yellow metal location tag 2.0' North of the monument.				
New Bearing Trees set:  17" diameter Douglas Fir tree whi All new bearing trees have a nail and "T", and a yellow metal location	ich bears S 22° E 10.8 scribed "T2S I and aluminum washer marked, "Till. on tag affixed.	R7W 1/4 S Co. Surv	S24	
Location & Comments: Corner logging road.	is located approximately 100' East o	of a new		
Firm / Agency	William to the first of the fir			SURVEYOR'S SEAL
Address: TILLAMOOK COUNTY	Y SURVEYOR'S OFFICE		ļ	
201 Laurel Avenue				
Tillamook, Oregon 97141				REGISTERED
			_	PROFESSIONAL AND SUBJECT OF THE PROFESSIONAL
Party Chief: Joe Jensen, P.L.S. 60067, Survey Supervisor				LAND SURVEYOR
	con of the found monument the reco	rd		Gasesh V. Cleuren
Notes: Digital images were taken of the found monument, the reco			İ	Journal
Witnesses: Danny R. McNutt, P.L.S. 49230, Tillamook County Surve Michael R. Rice, L.S.I. 16723, Survey Technician				OREGON JANUARY 10, 2006 JOSEPH V. JENSEN 68067 RENEWAL DATE: 06-30- 2011
				AUG 1 7 2010