## OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT Tillamook County Surveyor's Office

SECTION: SW Corner of	TOWNSHIP 2 South	RANC	RANGE 10 West		
Section 13		1		DATE: 11-04-10	
COUNTY: Tillamook CORNER DESIGNATION: The Southwest Section Corner of Section 13				(Please check one)	
	e Southwest Section Corner of Sect	ion 13,		Condition Report Only	
T. 2 S., R. 10 W., W.M.				Restoration	
			区	Rewitness	
				Unrecorded	
				Reset	
				Referenced Out	
Previous Rewitnesses, Restorations and Surveys, etc.: B.L.M. Field Notes Volume: OR-R0272 Page: 0066, (G.L.O. 2S10 Page 32, 1882); Rewitness Book 4, Page 93; Rewitness Card #459, B-820, Tillamook County Survey Records.  Found Monument(s) and Accessories (Condition & Source): Found 3" Tillamook County Surveyor brass cap in					
concrete. The monument is stamped as shown hereon. Found a 1" iron pipe with a babbit cap lying next to the monument. Found the very rotten remains of the white 4" x 4" x 60" wood post with a very rusted yellow metal location tag attached. (G.L.O.) — Found a 48" diameter X 7' tall rotten Hemlock stump (was a 20" Hemlock S 74° E 36 links, 1882) (G.L.O.) — Found a 54" diameter very rotten Hemlock stump (was a 30" Hemlock S 49° W 79 links, 1882) (Rewitness Book 4, Page 93) — Found a 20" diameter very rotten Hemlock stump (was a 10" Hemlock N 57° E 24.4') (Rewitness Card #459) — Found a 12" diameter Hemlock tree with healed face and a yellow metal location tag (was a 4" diameter Hemlock N 88° E 1.86' scribed "S13BT"). (Rewitness Card #459) — Found a 12" diameter Alder tree with visible bark scribing with a yellow metal location tag (was a 6" diameter Alder S 9° W 12.33' bark scribed "T2SR10WS23BTCS").					
Blanument Set (Procedures	and Description); Not Applicable.		Skoto	ch of Found Monument:	
				T2S R10W S14   S13 S23   S24 RS 287 1979	
Other new accessories set:					
New Bearing Trees:  *17" dia. Hemlock tree bears N 18° E 18.0', scribed "T2SR10WS13BT", tagged and painted.  *12" dia. Hemlock tree bears N 66° W 9.0', scribed "T2SR10WS14BT", tagged and painted.  Note: All new bearing trees have a nail and aluminum washer marked, "Till. Co. Surveyor" in face between B and T.  * Indicates a yellow metal location tag attached.  Location & Comments: This corner is located approximately 30' Westerly of an existing logging road. Yellow plastic monument tags marked "PLEASE PROTECT NEARBY SURVEY MARKER" were placed on trees					
along the road.					
Firm / Agency Address: TILLAMOOK COUN	ITY SURVEYOR'S OFFICE			SURVEYOR'S SEAL	
Party Chief: Joe Jensen, PLS				REGISTERED PROFESSIONAL LAND SURVEYOR	
Notes: Digital images were ta accessories.	ken of the monument and the new			Joseph V. Jenan	
	LS 49230, Tillamook County Survey   16723, Survey Technician	ОГ		OREGON JANUARY 10, 2008 JOSEPH V. JENSEN 60067	
				RENEWAL DATE: 06-30- 2011	

