## OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT Tillamook County Surveyor's Office

SECTION: SE COR 14	TOWNSHIP 1 North	RANGE 10 West	
COUNTY: Tillamook			DATE: 5- 27 -10
	ection Corner common to Sections 14	. 13.	(Please check one)
23 and 24 T. 1 N., R. 10 W., W.M.		) ,	Condition Report Only
			Restoration
<u> </u>			Rewitness
			Unrecorded
			Reset at surface
			Referenced Out
Previous Rewitnesses, Restorations and Surveys, etc: BLM Field Notes Volume: OR-R0122 Page 64, (GLO Book 1N10			
Pages 35-36) (1873), Hays Field Book "F", Page 91 same as Book 1, Page 12 (1886), Hays Field Book "F", Page 108 (1886),			
Book S3 Page 126 (1897), Rewitness Book 1 Page 399 (1959), Map B-419 (1959), Map A-1007 (1962), Map A-1034 (1962),			
Map B-477 (1963), Rewitness Book 6 Page 271 (1985), Tillamook County Survey Records.			
Found Monument(s) and Accessories (Condition & Source): Found a 3" diameter O.S.B.F. Brass Cap as restored in Book 1,			
Page 399. Cap is rotated 45° and is marked as shown hereon. Found a white painted cedar post lying near monument.  (G.L.O.) – Did not find the (10" Hemlock bears S 10° E 12 lks. [7.92']).			
(G.L.O.) – Did not find the (10 Hemlock bears S 10 E 12 lks. [7.92]).			
(G.L.O.) – Did not find the (14" Hemlock bears N 31° W 18 lks. [11.88"]).			
(Hays Book "F", Page 91) – Did not find the (20" Hemlock bears N 47° E 26 lks. [17.16']).			
(Book 1, Page 399) – Found 35" Hemlock, (was 16"), bears S 50 1/2° W 15.2' (S 47° W 14.7'), face healed, leaning downhill.			
(Book 1, Page 399) – Found rotten Hemlock Stump, 2' tall, (was 48"), bears (S 18° E 75.2'), no marks visible.			
(Book 1, Page 399) – Did not find the (8" Hemlock bears N 46° E 22.6').			
(Book 1, Page 399) – Did not find the (14" Hemlock bears N 5° W 33.2'),			
(Book 6, Page 271) – Found 18" Fir Stump, 1' tall, (was 9"), (bears N 55 1/2° E 57.3').  (Book 6, Page 271) – Found 23" Double-topped Hemlock, (was 14"), (bears S 3° W 23.5'), face healed with a yellow tag affixed.			
(Book 6, Page 271) – Found 23 Double-topped Herniock, (was 14 ), (bears S 3° W 23.5), face healed with a yellow tag affixed.  (Book 6, Page 271) – Found 45" "Schoolmarm" Spruce, (was 29"), (bears N 21° W 42.6'), face healed with a yellow tag affixed.			
[ ] Indicates converted record links to U.S. Survey Feet.			
( ) Indicates record information, Tillamook County Survey Records.			
Monument Set (Procedures and Description): N/A Sketch of Found Monument:			
			ATE BOARD ON
TIN RIOW (S)			
8 S14 S13 \R			
\\ S23 S24			
1985 R\$ 1998			
			1959
RS 401			
Now According not Cot 100 lb	-6		
<b>New Accessories set:</b> Set 120 lbs. of concrete in a 12" diameter cylinder around monument. Set 72" hat section post with a yellow metal location tag West 3.0' from the monument.			
New Bearing Trees set: N/A			
	nt is located approximately 60 feet W	est of	
a gravel logging road, on a steep hi	iiside.		
Firm / Agency			SURVEYOR'S SEAL
Address: TILLAMOOK COUNTY S	SURVEYOR'S OFFICE	ŀ	
201 Laurel Avenue			
Tillamook, Oregon 971	41		REGISTERED
Party Chief: Joe Jensen, P.L.S. 60	067 Survey Supervisor		PROFESSIONAL
Faity Cilies. Soe Sensen, P.L.S. 60	007, Survey Supervisor		LAND SURVEYOR
Notes: Digital images were tak	en of the monument and the access	ories.	Control of the Contro
Witnesses: Danny R. McNutt, P.L.S. 49230, Tillamook County Surveyor			Gaseth V. Gensen
Michael R. Rice, L.S.I. 16723, Survey Technician			OREGON
,			JANUARY 10, 2006
-			JOSEPH V. JENSEN
			60067



RENEWAL DATE: 05-30-2011