## OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT Tillamook County Surveyor's Office

SECTION: SE COR 24	TOWNSHIP 2 South	RANG	RANGE 10 West	
COUNTY: Tillamook		<u> </u>	DATE: 7- 23 -10	
CORNER DESIGNATION: The Section Corner common to Sections 24 and			(Please check one)	
25, T. 2 S., R. 10 W. and Sections		, a,,a		Condition Report Only
	, , ,	,		Restoration
			<u>-</u>	Rewitness
				Unrecorded
				Reset at surface
				Referenced Out
Previous Rewitnesses, Restorations and Surveys, etc: BLM Field Notes Volume				
Page 4) (1857), Book S3 Page 278 (1899), Book P16 Page 42 (1915), Book 6 Page 6 same as Map B-737 (1976), Map B-922 (1980), Book 7 Page 66 (1991), Tillamook County Survey Records.				
Found Monument(s) and Accessories (Condition & Source): Found a 3" diameter Crown Zellerbach Brass Cap, in concrete,				
up 0.5', in good condition, as restored in Rewitness Book 6, Page 6 (1976). The monument is stamped as shown hereon. Found a hat section post with a yellow metal location tag (North 1.5') from monument as set in Rewitness Book 7, Page 66.				
(G.L.O.) – Did not find the (Hemlock 20 ins. dia. bears N 52° E 54 lks. [35.64']).				
(G.L.O.) – Found rotten remains of a (Y. Fir 56 ins. dia. bears N 55° W 21 lks. [13.86']).				
(G.L.O.) – Did not find the (Hemlock 4 ins. dia. bears S 53 1/2° W 56 lks. [36.96']).				
(G.L.O.) – Found 72" Yellow Fir Stump, 7' tall, with nail, (bears S 42° E 60 lks. [39.6']). (Book 6, Page 6) – Found 38" Fir Stump, (was 30"), 3' tall, (bears N 42° E 18.5'), scribing visible.				
(Book 6, Page 6) – Found 36° Fit Stump, (was 30°), 3° tail, (bears N 42° E 16.5°), scribing visible.  (Book 6, Page 6) – Found 24" Fir Stump, 5' tail, (bears S 31° E 36.9'), healed over face and yellow metal location tag affixed.				
(Book 6, Page 6) – Found 16" Fir Stump badly rotten, (was 12"), 3' tall, (bears N 71° W 17.7'), healed over face.				
(Book 6, Page 6) – Found 30" Fir Stump rotten, 5' tall, (bears S 4° W 24.7'), scribing visible and a "Do Not Cut" tag affixed.				
[ ] Indicates converted value from links to feet.				
( ) Indicates record information, Tillamook County Survey Records.				
Monument Set (Procedures and I	Description): N/A	Sketch	ot S	et Monument:
				TELLERBACK
125 CA				
R10W R9W R				
/G S24 S19 · · ·				
→ S25 S30 →				
. 1976				
1976 L1C.				
New accessories set: Set 120 lbs. of concrete in a 12" dia. cylinder around the monument.				
New Bearing Trees set:				
* 9" dia. D. Fir bears N 72° E 26.6', scribed "T2SR9WS19BT", tagged and painted.				
* 9" dia. D. Fir bears S 57° E 27.0', scribed "T2SR9WS30BT", tagged and painted. * 10" dia. D. Fir bears S 21° W 21.4', scribed "T2SR10WS25BT", tagged and painted.				
	r, scribed "12SR10WS25B1", tagged   scribed "T2SR10WS24BT", tagged			1.
				e face hetween the scribed "R" and "T" and a
* Indicates an aluminum nail with a washer marked "Till. Co. Surveyor" was set in the face between the scribed "B" and "T" and a yellow metal location tag was affixed.				
Location & Comments: Monument is located approximately 100' NW of a				
	approximately 80' SW of the toe of			
slope.				
Firm / Agency				SURVEYOR'S SEAL
Address: TILLAMOOK COUNTY SURVEYOR'S OFFICE 201 Laurel Avenue				PEO IO TENE
Tillamook, Oregon 97141				REGISTERED PROFESSIONAL
. mamoon, Oregon 971				LAND SURVEYOR
Party Chief: Joe Jensen, P.L.S. 60067, Survey Supervisor			1	
Notes: Digital images were taken of the monument and the new trees.				Gaseful. Gensen
Witnesses: Danny R. McNutt, P.L	.S. 49230, Tillamook County Survey	or	1	OREGØN JANUARY 10, 2006
, ·	l. 16723, Survey Technician			JOSEPH V. JENSEN
	•			60067



RENEWAL DATE: 08-30- 2011