OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT Tillamook County Surveyor's Office

SECTION: SE Sec 7	TOWNSHIP 1 South	RANGE 8 West		
COUNTY: Tillamook		<u> </u>		DATE: 12-20-10
CORNER DESIGNATION: The Se	ection Corner common to Sections 7.	8. 17		(Please check one)
and 18, T. 1 S., R. 8 W., W.M.		, -,		Condition Report Only
		ì		Restoration
			×	Rewitness
				Unrecorded
				Reset at surface
				Referenced Out
Previous Rewitnesses, Restorati	ons and Surveys, etc: BLM Field N	lotes Vol	ume	: OR-R0266 Pages 559 - 560, (GLO Book
1S8 Page 103) (1883), BLM Field Notes Volume: OR-R0575 Page 35, (GLO Book 1S8 Page 145) (1958), Rewitness Card #168				
(1984), Survey Map B-3414 (2010), Tillamook County Survey Records.				
Found Monument(s) and Accessories (Condition & Source): Found a 3" diameter B.L.M. Brass Cap, good condition, in				
concrete, as restored in BLM Field Notes Volume: OR-R0575 Page 35 (1958). Monument is stamped as shown hereon. Found				
hat section post North 2.0' from the monument.				
(G.L.O. 1883) – Did not find the (6" Maple bears N 59° W 19 lks. [12.54']). (G.L.O. 1883) – Did not find the (14" Hemlock bears N 66° E 13 lks. [8.58']).				
(G.L.O. 1883) - Did not find the (14 Hemlock bears N 66 E 13 lks. [6.6/]).				
(G.L.O. 1883) – Did not find the (6" Barberry bears S 22° W 21 lks. [13.86']).				
(G.L.O. 1958) – Found 48" Hemlock Stump (was 26"), 4' tall, (bears N 18 3/4° E 41 lks. [27.06']), no visible marks.				
(G.L.O. 1958) – Found 48" Spruce (was 30"), (bears S 84° E 43 lks. [28.38']), healed face.				
(G.L.O. 1958) - Found rotten Spruce (was 17"), (bears S 22 1/4° W 103 lks. [67.98']), scribing partially visible.				
(G.L.O. 1958) – Did not find the (18" Spruce bears N 54° W 176 lks. [116.16']).				
() Indicates record information, Tillamook County Survey Records.				
[] Indicates converted value from links to feet. Monument Set (Procedures and Description): N/A Sketch of Found Monument:				
Monument Set (Procedures and I	Description): N/A	Sketch	OT F	ouna monument:
				CADASTRAL
Co. 54 \$250 FOR RELIED				The state of the s
/ with tis row to the time to				/ Just TIS R8W Trick
{ S7 S8 \				S7 S8
S18 S17				
1958 LAND MANAGERET				1958 65
				OF LAND MANY
	i			
New Accessories set: N/A	Calabata Apara Mahampungangan andara sa mahampungan andara sa mahampungan andara sa mahampungan andara sa maham	non-contributed to be because		A CONTRACTOR OF THE PROPERTY O
New Bearing Trees Marked:				
* 10" diameter Fir bears S 28° W 65.5', scribed "T1SR8WS18BT", yellow metal location tag affixed and tree painted.				
* 14" diameter Hemlock bears N 9° E 41.7', scribed "T1SR8WS8BT", yellow metal location tag affixed and tree painted.				
* Indicates an aluminum nail with a washer stamped "Till. Co. Surveyor" is set in the face between the scribed "B" and "T".				
	nt is located approximately 50' East	of a 3'		
wide creek running North/South.				
Firm / Agency				SURVEYOR'S SEAL
Address: TILLAMOOK COUNTY SURVEYOR'S OFFICE				
201 Laurel Avenue				
Tillamook, Oregon 971	41			REGISTERED
Party Chief: Joe Jensen, P.L.S. 60067, Survey Supervisor			-	PROFESSIONAL
arty officer soc sensen, r.L.s. 60007, Survey supervisor				LAND SURVEYOR
otes: Digital images were taken of the monument and its accessories.			1	Joseph V. Jeusen
Witnesses: Danny R. McNutt, P.L.S. 49230, Tillamook County Surveyor			1	The second secon
•	I. 16723, Survey Technician	, 5,		OREGON JANUARY 10, 2006
		20 to 40 to 10		JOSEPH V. JENSEN
				60067
				RENEWAL DATE: 03-30-2011

