OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT Tillamook County Surveyor's Office

SECTION: The Southeast TOWNSHIPS: 1 North, 1 South RANGE: 9 West				
COUNTY: Tillamook			DATE: 05-19-11	
CORNER DESIGNATION: The Section corner common to Sections 31			(Please check one)	
and 32, Township 1 North, Range 9 West, W.M.; and Sections 5 and 6,			Condition Report Only	
Township 1 South, Range 9 West, W.M., Tillamook County, Oregon.			Restoration	
			园	Rewitness
			Unrecorded	
				Reset at surface
				Referenced Out
Page 72, Rewitness Book 6, Page 483A and 483B, Tillamook County Survey Records. See Partition Plats P-369, P-464, P-661; Survey Maps B-224, B-663, B-952, B-1939, B-1546, A-1105, A-1241, A-1975, A-5369, Tract Book S3, Page 292; Field Book AMA 9, Page 49 and 50, Tillamook County Survey Records. Found Monument(s) and Accessories (Condition & Source): Found a 3" diameter Brass cap 18" below the gravel road surface. This monument was found to be upright and in position, but the stamping on the cap is now illegible. Found a 7' tall broken snag at position with tree remains East of snag (was a 49" diameter Spruce tree with face overgrown and a B.L.M. location poster attached bearing N. 55° E 158 lks. See Rewitness Book 6, Page 483A). Found a 79" diameter Spruce tree at position (was a 49" diameter Spruce, face overgrown, location poster attached bearing N. 33 1/2° W. 53 lks. See Rewitness Book 6, Page 483A). Found a 22" diameter Maple tree with a healed face now bearing S. 53° E at a distance of 34.11'. (Was a 15" Maple tree bearing S. 53° E 34.70'. See Rewitness Book 6, Page 483A). This bearing tree is bowed and appears to be moving down the hill towards the road. Found a 16" diameter Alder tree with bark scribing visible with a B.L.M. tag now bearing S. 18° W at a distance of 27.78'. (Was a 9" Alder tree bearing S. 18° W 28.85' See Rewitness Book 6, Page 483A). This bearing tree is bowed and appears to be moving down the hill towards the road. The 10" Alder and 12" Alder bearing trees as described in Rewitness Book 6, Page 483A are now gone. WGS84 Geodetic Position = Latitude North = 45° 31' 16.29344", Longitude West = 123° 49' 25.03315". Oregon North Zone '83-'91 NAD State Plane Coordinates in U.S. Feet: Easting = 7350462.462, Northing = 693632.206. Convergence = -2° 21' 32.88090", Combined Scale Factor = 0.99991450.				
Cap in a 10" diameter cast iron	and Description): 2" diameter Bras in monument box and 120 pounds of ad surface. The monument is stamp	ed	illegil this t Book	ch of Found Monument: Brass Cap was ble, but I found the centerpunch. I believe to be the BLM monument set in Rewitness 3, Page 109. I left this brass cap at ion as an underground monument.
New accessories set: Reset a 72" Hat Section post with yellow metal location tag South 10° East 11.00' from monument. New Bearing Trees Set: No new bearing trees were set.				

Location & Comments: The monument is located in the southerly track of the Kilchis River Forest Road at approximately the intersection of a gravel road Northerly that goes to a gravel bar.

Firm / Agency

Address: TILLAMOOK COUNTY SURVEYOR'S OFFICE

201 Laurel Avenue

Tillamook, Oregon 97141

Party Chief: Joe Jensen, PLS 60067, Survey Supervisor,

Deputy County Surveyor

Notes: Digital images were taken of the found monument, the new monument, the record bearing trees and new accessories.

Witness: Danny R. McNutt, PLS 49230, Tillamook County Surveyor; Michael R. Rice, L.S.I. 16723, Survey Technician SURVEYOR'S SEAL

REGISTERED **PROFESSIONAL** LAND SURVEYOR

Goseph V. Gensen OREGON JANUARY 10, 2006 JOSEPH V. JENSEN

60067 MENEWAL DATE: 08-30-2013

