## OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT Tillamook County Surveyor's Office

SECTION: 1, 12, 6 and 7;	TOWNSHIP 1 South;	RANG	RANGES 10 West and 9 West;		
COUNTY: Tillamook		<u> </u>		DATE: 05-31-11	
CORNER DESIGNATION: The Section Corner common to Sections 1				(Please check one)	
and 12, T1S R10W; Sections 6				Condition Report Only	
				Restoration	
			E	Rewitness	
				Unrecorded	
			6	Referenced Out	
Previous Rewitnesses, Restorations and Surveys, etc.; BLM Field No					
Tillamook County GLO Book T1S R10W, Page 7; Tillamook County Rewitness Card #183 (1972 and 1985); Rewitness Book 5, Page 283; Rewitness Book 4, Page 43; Tillamook County Survey Records. See previous rewitness cards for a					
more detailed history.					
Found Monument(s) and Accessories (Condition & Source): Found a 3" diameter Tillamook County brass cap upright and in good condition, flush with the level of the existing gravel driveway. I dug up the found monument and reset the monument 3" to 4" below the existing driveway surface. I then placed 180 pounds of concrete and a 12" diameter cast iron monument box with lid around the monument. The monument is starmped as shown hereon and as shown on Rewitness Card #183.  Found power pole #128843 (was Power pole #2-01-10 on Rewitness Card #183 with a scribed triangle △ bearing South 60° West 49.35'), at record position.  Found power pole #071800 (was Power pole #2-01-09 on Rewitness Card #183 with a scribed triangle △ bearing South 54° East 33.15'), at record position.  Found the southwest corner of a storage warehouse (bearing North 54° West 25.32' on Rewitness Card #183), at record position.  Found the southeast corner of a storage warehouse (bearing North 56° East 23.61' on Rewitness Card #183), at record position.  WGS84 Geodetic Position = Latitude North = 45° 30' 25.73866", Longitude West = 123° 50' 36.61499". Oregon North Zone '83-'91 NAD State Plane Coordinates in U.S. Feet: Easting = 7345158.632, Northing = 688726.653. Convergence = -2° 22' 16.19925", Combined Scale Factor = 0.99991409.					
Monument Set (Procedures a	and Description): Not Applicable.		Sket	ch of Found Monument:	
				COUNTY I 1 S R1 S6 S12 S7 LS 793 1985	
Other new accessories set: No new accessories were set.					
New Bearing Trees: No bearing trees set.					
Location & Comments: This corner is located in an existing driveway to a warehouse at the intersection of Alderbrook Road and Kilchis River Road.					
Firm / Agency Address: TILLAMOOK COUN 201 Laurel Avenue				SURVEYOR'S SEAL	
Tillamook, Oregon	97141			PROFESSIONAL LAND SURVEYOR	
Party Chief: Joe Jensen, PLS	outor, ourvey oupervisor		<u> </u>	Gaseph V. Cheusen	
Notes: Digital images were tak	en of the new monument and		<b>F</b>	OREGON	
accessories.			JANUARY 10, 2006		
ARIA	O 40000 Till		l	JOSEPH V. JENSEN	
	<sub>-</sub> S 49230, Tillamook County Surveyo 16723, Survey Technician	or I	1	60067 GENERAL DATE: 05 20 2013	
Wildlas R. Rice, LSI	10720, Survey Technician			RENEWAL DATE: 08-30-2013	