OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT Tillamook County Surveyor's Office

SECTION: 14	TOWNSHIP 4 South	RANGE 7 West		
COUNTY: Tillamook			DATE: 10-4-11	
CORNER DESIGNATION: The Quarter Corner common to Sections 14				
23, T. 4 S., R. 7 W., W.M.		T CITIC		Condition Report Only
				Restoration
			<u>-</u>	Rewitness
				Unrecorded
				Reset at surface
				Referenced Out
Previous Rewitnesses, Restorations and Surveys, etc: BLM Field Notes Volume: OR-R0118 Page 782, (GLO Book 4S7 Page 6) (1873), Map A-1614 (1968), Tillamook County Survey Records.				
Found Monument(s) and Accessories (Condition & Source): Found the original stone approximately 16" x 12" x 12" marked 1/4 on bottom. Stone is lying down and loose, it has apparently rolled downhill, out of position. We remonumented the position with a Tillamook County Brass Cap using the found bearing trees from Map A-1614 (1968) and set the original stone beside. (Map A-1614) – Found 25" dia. Fir (was 14") (bears N 10° W 20.3') with healed scar and yellow metal location tags. (Map A-1614) – Found 18" dia. Fir (was 8") bearing S 23° E (S 20° E) (9.4') with healed scar and yellow metal location tags. () Indicates record information, Tillamook County Survey Records.				
Monument Set (Procedures and I We sawed out the healed scars of the face scribed in 1968. Set an alu "Till. Co. Surveyor" in the scribed famonument. Using Survey A-1614 was corners to find Leo Martin's record the tree. Adding the record radius to calculated a distance/distance interalso fits record angle structure well.	the found bearing trees to expose iminum nail and washer marked, ices for reference to re-position be verified accessories at other distances to be to the center of o our found face distances we section for position. The solution	Sketch of Set Monument: Sketch of Sketch		
New Accessories set: Set 120 lbs. of concrete in a 12" diameter cylinder around set monument. Set 72" hat section post with a yellow metal location tag, South 3.0' from monument.				
New Bearing Trees Marked: *19" dia. D. Fir bears N 55° E 12.4', scribed "T4SR7W1/4S14BT", tagged and painted. *12" dia. D. Fir bears S 46° W 39.4', scribed "T4SR7W1/4S23BT", tagged and painted. * Indicates an aluminum nail with washer marked, "Till. Co. Surveyor" in the face of the blaze between the scribed "B" and "T". Also, a yellow metal location tag affixed in an upper blaze. Location & Comments: Monument is located approx. 25' East of Logging				
Road 4-7-15.1.				
Firm / Agency Address: TILLAMOOK COUNTY SURVEYOR'S OFFICE 201 Laurel Avenue Tillamook, Oregon 97141				SURVEYOR'S SEAL
Party Chief: Joe Jensen, P.L.S. 60067, Deputy County Surveyor				and the state of t
Notes: Digital images were taken of the monument and its accessories. Accessories were tied with a Topcon GPT 3005 Total Station. Witnesses: Danny R. McNutt, P.L.S. 49230, Tillamook County Surveyor Michael R. Rice, L.S.I. 16723, Survey Technician				PROFESSIONAL LAND SURVEYOR Danny R Mc Nutb OREGON JULY 11, 2000
				DANNY R. MCNUTT 49230 RENEWAL12-31-20/2

