OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT Tillamook County Surveyor's Office

SECTION: 10 and 15	TOWNSHIP 1 South	RANGE 9 West		
COUNTY: Tillamook			DATE: 11-15-11	
CORNER DESIGNATION: The Quarter Corner common to Sections 10 and		10 and	(Please check one)	
15, T. 1 S., R. 9 W., W.M.			Condition Report Only	
			Restoration	
		×	Rewitness	
			Unrecorded	
			Reset at surface	
;			Referenced Out	
Previous Rewitnesses, Restorations and Surveys, etc: BLM Field Notes Volume: OR-R0053 Page 297, (GLO Book 1S9 Page 59) (1857), BLM Field Notes Volume: OR-R0575 Page 226, same as Rewitness Book 3 Page 148 (1958), Map A-1100 (1963), Map B-672 (1974), Rewitness Card #194 (1988), Tillamook County Survey Records. Found Monument(s) and Accessories (Condition & Source): In 1958, in a dependent resurvey of a portion of T. 1 S, R. 9				
W., Bureau of Land Management found no remaining evidence of the original corner or its accessories. A monument was set at proportionate distance along the section line. Found 3" dia. B.L.M. Brass Cap, up 0.5' in a 10" concrete cylinder with a rock collar. The monument is stamped as shown hereon. Found a hat section post South 1.9' from monument. (BLM) – Found 20" rotten Fir Stump, was (22" Fir), 18" tall, bears (N 67° W 8 1/2 lks. [5.61']), no visible markings. (BLM) – Found 12" rotten Fir Stump, 18" tall, bears (S 58° E 37 lks. [24.42']), no visible markings. (Rewitness Card #194) – Found 25" dia. Spruce, was (8"), bears (N 10° W 8.66') healed face and tag healed over. (Rewitness Card #194) – Found 30" dia. Spruce, was (10"), bears (N 85° W 18.41') healed face and tag healed over. () Indicates record links converted to feet.				
Monument Set (Procedures and	l Description):	Sketch of F	ound Monument:	
		CADASTRAL SCANISTRAL STAND TIS R9W 1/4 S10 1/4 S15 1958 LAND MANAGEMENT LAND MANAGEMENT CADASTRAL SCANISTRAL SCANIS		
New Accessories set: Added yellow metal location tags to the found hat section post and the found bearing trees from Rewitness Card #194. Added 100 lbs. of concrete in a 12" dia. Cylinder around monument. Reset rock collar.				
New Bearing Trees Marked: *15" dia. Fir bears N 49° E 30.9', scribed "T1SR9W1/4S10BT", tagged and painted. *18" dia. Hemlock bears S 21° W 39.0', scribed "T1SR9WS15BT", tagged and painted. * Indicates an aluminum nail with washer marked, "Till. Co. Surveyor" in the face of the blaze between the scribed "B" and "T". Also, a yellow metal location tag affixed in an upper blaze. Location & Comments: Monument is located on the main ridge dividing the Kilchis and Wilson River drainages. Approx. 300' west of gravel spur logging road.				
Firm / Agency Address: TILLAMOOK COUNTY SURVEYOR'S OFFICE 201 Laurel Avenue Tillamook, Oregon 97141			SURVEYOR'S SEAL	
Party Chief: Joe Jensen, P.L.S. 60067, Deputy County Surveyor			REGISTERED PROFESSIONAL	
Notes: Digital images were taken of the monument and its accessories.		ssories.	LAND SURVEYOR	
Witnesses: Danny R. McNutt, F	P.L.S. 49230, Tillamook County Surve S.I. 16723, Survey Technician		Jasoph V. Jensen OREGON JANUARY 10, 2008 JOSEPH V. JENSEN 60067 RENEWAL DATE: 08-38-2013	



G:\completed restorations\T1SR9WQuarterSec10,15.doc