OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT Tillamook County Surveyor's Office

SECTION: Northeast corner TOWNSHIP: 3 North RANGE: 10 West					
of Section 34					
COUNTY: Tillamook			DATE: 09-14-12		
CORNER DESIGNATION: The Section Corner common to Sect 26, 27, 34, and 35, T. 3 N., R. 10 W., W.M.			 	(Please check one)	
			무	Condition Report Only	
				Restoration	
·			区	Rewitness	
			므	Unrecorded	
			図	Reset at surface	
			ļΩ	Referenced Out	
Previous Rewitnesses, Restorations and Surveys, etc: BLM Field Note Volume: OR-R0122 Page 0183 (1873); (GLO 3N10W Pg. 18) (1873), Rewitness Card #139; Book 6, Page 488 (1990); Tillamook County Survey Records.					
Found Monument(s) and Accessories (Condition & Source): Found a 3" diameter Tillamook County brass cap in 10" monument box encased in concrete. Found a Hat Section post at record position (East 19.25' Rewitness Book 6, Page 488). Found a 1-1/4" iron rod in gravel lane at the P.I. of Tideland Road (Southerly 420.2' Rewitness Card #139). Did not search for the bent 3/4" iron rod located Northerly 1663.1' (Rewitness Card #139).					
Monument Set (Procedures a	and Description): Set a 2"	Sketch	of S	et Monument:	
diameter brass disk inside the found monument box with					
concrete at the road surface. The set 2" diameter brass disk is					
stamped as shown hereon. We referenced the found monument				DUNTY	
with two mag nails with center punch at 1.11' Northerly and 1.02' Easterly. Two (2) reference monuments being 5/8" X 30" rebar with a red plastic cap stamped "TILLAMOOK CO			151	NKIOW A	
rebar with a red plastic cap stamped "TILLAMOOK CO				/1526 <u>6</u>)	
SURVEY" were set at the bearings and distances described				1 5 3 5 7	
helow. An assumed compass backsight bearing of North was					
used to set the two (2) reference monuments. The reference			2012		
monuments were set in existing fence lines on both the East and			_		
West sides of Tideland Road.					
,					
Now a consequence = 4. Cat C / 0	22 V 2022 pohor with a red plantic com	ctompod	segr:1	llamook Co Survou" as a reference	
New accessories set: Set a 5/8" X 30" rebar with a red plastic cap stamped "Tillamook Co. Survey" as a reference accessory to the corner monument that bears South 48° East 27.32'. Set a 5/8" X 30" rebar with a red plastic cap stamped					
"Tillamook Co. Survey" as a reference accessory to the corner monument that bears South 37° West 34.62'.					
New Bearing Trees set: No new bearing trees set. There are no available trees in the area.					
Location & Comments: Corner is located in the centerline paint stripe of					
Tideland Road approximately ¼ mile South of the Nehalem sewer plant.					
				SURVEYOR'S SEAL	
TILLAMOOK COUNTY SUI	RVEYOR'S OFFICE			the second is the second and the transfer of the second and the se	
201 Laurel Avenue					
Tillamook, Oregon 97141				REGISTERED	
				PROFESSIONAL	
Party Chief: Joe Jensen, P.L.S. 60067, Survey Supervisor; Deputy County			/	LAND SURVEYOR	
Surveyor				Across of A	
				Jaseph V. Gensen	
Notes: Digital images were taken of the subsurface and surface				OREGON JANUARY 10, 2006	
monuments.				JOSEPH V. JENSEN	
The state of the s		<u> </u>		60067	
				RENEWAL DATE: 08-30- 2013	
TYPE TO DESCRIPTION OF THE STATE OF THE STAT					
Witnesses: Danny R. McNutt, P.L.S. 49230, Tillamook County Surveyor.					
				100K C	