WEYERHAEUSER GOVT. CORNER VISITATION

SECTION 36 TOWNSHIP 2S RANGE 7W W.M. BLM ID# 640100	
DLC CORNERSOUTH GUARTER	
DATE 8/04/16 X CONDITION REPORT RENEWED	
PREVIOUS RENEWALS/SURVEYS, ETC.: B-2241 AND B-3087 MONUMENT (S) AND ACCESSORIES FOUND, CONDITION AND (ORIGIN)	
2 3/8" BRASS CAP, ON A 1 3/8" IRON PIPE, FLUSH IN MOUND OF STONES. A 3/4" FIBERGLASS POST WAS FOUND ON THE GROUND. IT WAS PLACED 0.8' NORTH OF MONUMENT	(B-2241)
21" D.FIR, WITH A HEALED FACE AND SILVER. B.T. TAG, BEARS N17°E, 44.1' (17" D.FIR, BEARS N17°E, 44.1' - B-2241)	(B-2241)
15" D.FIR, WITH A HEALED FACE AND W.W.I. B.T. TAG, BEARS S30 °E, 17.3' (12" D.FIR, BEARS S30 °E, 17.3' - B-2241)	(B-2241)
19" D.FIR, WITH A HEALED FACE AND W.W.I. B.T. TAG, BEARS S10 W, 3.7' (14" D.FIR, BEARS S10 W, 3.7' - B-2241)	(B-2241)
24" D.FIR, WITH A HEALED FACE AND W.W.I. B.T. TAG, BEARS N40 W, 33.3' (17" D.FIR, BEARS N40 W, 33.3' - B-2241)	(B-2241)

MONUMENT (S) SET (PROCEDURES AND DESCRIPTION)

NONE

NEW ACCESSORIES:

NONE

COMMENTS:

ALL FACES WERE PAINTED BLUE. AS WAS A 6" BAND AROUND THE TREES.

DISTANCES TO THE BEARING TREES WERE MEASURED WITH A 75' BUCKERS TAPE TO AN EXISTING NAIL AT THE SIDE CENTER.

BEARINGS WERE COMPARED WITH A HAND COMPASS WITH THE DECLINATION SET AT 16 °E.

MONUMENT DETAIL:

