

CHAINS

c
 $\frac{1}{4}$ cor bet
 12,13
 T2S RLOW

Found old burmt spruce limb marked $\frac{1}{4}$ S in fence line but no BT's were found.
 New BT'S
 5" hem S33-30E, 17.3 ft
 4" hem N71E, 24.7 ft
 In the presence of Glenn H. Marcussen and Francis L. Smith,
 Jan., 1954

c
 Sec cor 13,
 14,23,24
 T2S RLOW

Found 1" galv. pipe with 2" adapter filled with babbitt. Found BT'S insec. 14,23 & 24 and a made a new BT in sec 13 of a 10" hem, N57E, 24.4 ft.
 In the presence of G.H.Marcussen and Francis L. Smith,
 Jan, 1954

v
 $\frac{1}{4}$ cor bet
 13 and 14
 T2S RLOW

Found old hem chopped out mark $\frac{1}{4}$ S. Old BT's were completely rotted away, no marks were found.
 New BT's
 15" hem S29E, 14.4 ft
 9" hem S86W, 12.0 ft.
 In the presence of G. H. Marcussen and Francis L. Smith,
 Dec., 1953