

(54)

CHAINS
FEET

2624.4 The 1/4 corner bet. Secs. 13 & 18.

At the edge of stone marking the corner set an iron pipe 1 1/2 inches in diam. 3 ft. long, filled with charcoal, with an Oregon State Board of Forestry bronze cap stamped 1/4 S13 S18 1949 199.

Relative to the bearing of the random line, the true line to the corner of Sections 12, 13, 7, 18 bears N 0 3/4' E.

Beginning new measurement.

2652.9 The corner to Secs. 12, 13, 7, 18 T1N R5 & 6 W WM.

The above work done by Don Davis, transitman, Bruce Thomas and Wayne Frank, chainmen, Douglas Rogers, flagman, under my direction.

September 1, 1949

Lyle E. Beyers
Forest Engineer

