

CHAINS

At the point for corner

Set a 1½ inch iron pipe, 3 feet long, filled with charcoal, with an Oregon State Board of Forestry bronze cap stamped: W 1/16 S9 S16 1950 199.

from which:

A fir snag, 20 inches in diam., bears N 71° W, a distance of 60.6 feet, scribed: W 1/16 S 9 199 BT.

Placed a metal location poster on a 42 inch fir snag marked: Sec 9/16 T1N R7W W 1/16 Cor. 32.3 ft. N 78° W.

2690.6

Point for ¼ corner between sections 9 & 16 by proportionate distance.

Adjustment from temporary stake 2624.8 -- North 84.5 feet, East 67.3 feet.

At the point for corner

Set a 1½ inch iron pipe, 3 feet long, filled with charcoal, with an Oregon State Board of Forestry bronze cap stamped: ¼ S9 S16 1950 199.

from which:

A cedar stub, 30 inches in diam., bears S 31° W, a distance of 10.0 feet, scribed: 1/4 S 16 199.

A Fir snag, 72 inches in diam., bears N 24° 30' W, a distance of 16.4 feet, scribed: ¼ S 9 199.

Placed a metal location poster in the 72 inch fir snag & marked it: Sec 9/16 T1N R7W ¼ cor 16.0 Ft S 24° 30' E.

5381.1

The corner to sections 9, 10, 15, & 16.

\*\*\*\*\*

Beginning at the corner to secs. 8, 9, 16, & 17.

Northerly, in a traverse to

The ¼ cor. between secs. 8 & 9, determined by

A bronze cap set in concrete and stamped: T1N R7W ¼ SECT COR.

from which:

A 4 x 4 inch white cedar post bears West a distance of one foot, marked USBM, and scribed, ¼ cor, on the north side.

Relative to the calculated bearing of the random line bet. secs. 9 & 16, the true line bet. the cor. to sections 8, 9, 16 & 17 & the ¼ cor. to secs. 8 & 9 bears N 0° 45' E, a distance of 2668.9 ft.