

CHAINS

Established Corners: Page (117)

7.

Section corner $\frac{16}{21} | \frac{15}{22}$ T3N, R10W, WM.

Original:

Post in Creek, From which

45" Cedar N4°E 47 Lks.

32" Hemlock N65°W 41 "

30" Hemlock S10°E 42 "

Not found

No evidence that anyone has ever found this cor. altho. all cedar stumps in vicinity have been chopped out. I conclude that the line north of $\frac{21}{28} | \frac{22}{27}$ was never run.

Established Corner: By proportionate measurement E and West from $\frac{16}{21}$ to $\frac{15}{22} | \frac{14}{23}$ and North and South from $\frac{9}{10} | \frac{10}{15}$ to $\frac{21}{28} | \frac{22}{27}$, which was computed at the intersection of two old line fences East from the $\frac{16}{21}$ $\frac{21}{28}$ and North from the $\frac{16}{21}$ $\frac{28}{27}$, both of which are generally accepted as being on the original section lines.

Set a $\frac{3}{4}$ " x $\frac{3}{4}$ " 61 pipe, from which

13" Hemlock S51°41'E 51 $\frac{1}{2}$ ft scribed 522 E

18" spruce N89°44'W 54 $\frac{1}{2}$ " " 521 E

April 13, 1951

Running N84°42'W along the section line toward $\frac{16}{21}$

I find a line of blazes, probably

117 cut by Markham and Callow.

