

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One-quarter corner common to sections 17 and 18, T2N, R9W, WM.,
Tillamook County, Oregon.

ORIGINAL

Post, now missing, from which a:

10" Fir bears S87E 8 lks; now 20" Fir, exposed scribe
marks.

8" Fir bears N66W 15 lks, now 22" Fir.


RESTORED CORNER

Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked
"OREGON STATE BOARD OF FORESTRY 1/4 S18 S17 1952 2311" 2 1/2" in
ground. Raised mound of stone around corner pipe.

Placed an Oregon State Board of Forestry metal location poster
on Original BT now 20" Fir and marked it: Sec 17 T2N R9W
1/4 Cor 4-8Ft. N87W.

Dated August 15, 1952

This corner was restored by Don D. Davis, under
my direction. Don D. Davis Assistant Forest Engineer



Present and witnessed by Richard A. Morris
Richard A. Morris Compassman

Present and witnessed by Robert A. Young
Robert A. Young Chairman