

Line between Sections 8 & 9 Township 1 North Range 9 West, Tillamook Co.

- North on true line between Sections 8 and 9, T. 1 N R 9 W.
- Station
0700 Section corner 8, 9, 16 and 17 T. 1 N R 9 W.
- 24748.5 Restored 1/4 section corner 8 & 9 T. 1 N R 9 W. Monumented corner with iron pipe 1" x 30" and referenced as follows:
18" cedar N 42° E. 28.0 ft. Scribed 1/4 S 9 B.T.
24" cedar N 20° E. 24.3 ft. " 1/4 S 9 B.T.
Wm. Jordan, Dave Bowden
July 5, 1960
- 36772.7 Established 1/16 section corner. Monumented with iron pipe 1" x 30" and referenced as follows:
30" hemlock N 20° W. 20.7 ft. Scribed N 1/16 S 8 B.T.
17" alder N 16° E. 3.5 ft. Scribed N 1/16 S 9 B.T.
Wm. Jordan, Dave Bowden
July 6, 1960
- 48797.0 Section corner 4, 5, 8 and 9, T. 1 N R 9 W.
Set by stream ties as recorded in original field notes and as agreed between the Longview Fibre Company and State of Oregon. Monumented corner with an iron pipe 1" x 30" and referenced as follows:
11" Alder S 10° W. 5.2 ft. Scribed S 8 B.T.
13" Hemlock S 66° E. 87.1 ft. " S 9 B.T.
7" Hemlock N 0° 30' E. 53.9 ft. " S 4 B.T.
Jordan, Miller, Richard Morris,
E. Nyland, June 17, 1960.
Var. 21° 30' E.

LONGVIEW FIBRE COMPANY

By Olin R. Miller, Forest Engineer
February 27, 1961