

CHAINS

117

CA Sec 30 2S10

Found old spr limb with scribing
on it "4 CS" 12" High & A 1/2" Iron
Pipe Back Bore 13" Northly of Post
Old Bearing Tree Fit The Post
Old Bearing Trees AIE

14" Hem N 50 E 35 1/2

Now 24 Hem stump scribing still good

20" Hem N 19-30 W 40°

32" Hem still green Did Not Cut open
Has Well Healed Face

I Set A 2" Iron pipe in place
of old spr limb Left spr limb
Be Side Pipe. Do Not Need
New Bearing Trees

G Aruther

S Skinner 4-20-66

See WEA Notes

OK - G. Reichers

T. M. Kroy

Marked CS

BOOK 5

11/10/71