

County Surveyor's Record, Tillamook County, Oregon

CHAINS

- (MAPS)
- B-317 Anderson Subdivision Eng # 1697 Section 13 T2SR10W
 - B 155 # 156 Walker R.S. 150 for Rieger
 - F-2-11 Anderson Bewley Creek County Road
 - C-29 P.L. Wise C. Eng. Strese Subdivision
 - B-472 CG Collard R.S. 376 Subdivision Sec 18 T2SR0W
 - A-2119 # A-1829 J.L. Carlich R.S. 287 Co-ord Tie To Corner

(GLO T2SR10W)
Pages 3 & 4

(Book) 1 (Page) 95
S3 278
P16 60

Refer to field note bin for Co-ordinate sheet of Subdivision of Section 13 T2SR10W by W.E. Anderson (Eng # 1697). Also see MAP B-317

Sec. Corner

2510	255
13	18
24	19

Sec. 18+19 T2SR9W

Sec. 13+24 T2SR10W

Witnessing by WEA (Book 1 Page 95) Shows Witnessing To Walkers corner -- Anderson then subdivided Section 13 and found Walkers corner incorrectly set. The witness values were never corrected on record until now--1972.

Refer to Co-ord sheet for more accurate tie
(Approximate Value)
N 14 1/2° W 38'

