



OREGON PUBLIC LAND CORNER REPORT/RESTORATION REPORT
Tillamook County Surveyor's Office

SECTION: 5	TOWNSHIP: 1 North	RANGE: 10 West
COUNTY: Tillamook		DATE: 6/1/2007
CORNER DESIGNATION: Initial Point Ridge Crest		(Please Check One)
		<input type="checkbox"/> Condition Report Only
		<input type="checkbox"/> Restoration
		<input type="checkbox"/> Rewitness
		<input type="checkbox"/> Not Found
		<input checked="" type="checkbox"/> Reset
		<input type="checkbox"/> Referenced Out
Previous Rewitnesses, Restorations, Surveys, etc.: Rewitness Card Number 20; Survey Map A-8078		
Found Monument(s) and Accessories(Condition & Source): Contractor reported monument gone and a new concrete retaining wall in its place. I set new monument as indicated below in top of new concrete retaining wall.		
Monument Set(Procedures & Description): I set a 2 1/2" Brass Cap with a 2" stem in a 1/2" drill hole in top of new concrete retaining wall at the SE end of the wall, stamped "2007 INT PT RIDGE CREST LS 2507". I used the same two centerline monuments in Crest Terrace to re-set this new Brass Cap (the same method as used on Map A-8078).		
Other New Accessories Set: None - see Survey Map A-8078		
New Bearing Trees: None		
Location & Comments: At the South end of Crest Terrace, at the intersection of Terrace Drive, on Pacific View Estates, above the town of Rockaway Beach.	Surveyor's Stamp  Renewal date 6-30-09	
Firm/Agency: Bayside Surveying		
Address: 11765 Hwy 101 S. Tillamook, OR 97141		
Party Chief: Terry L. Jones, PLS 2507		
Notes: In Pacific View Estates file in my office		Office Use Only
Witness(es): Dallis Esplin		