

TOWNSHIP CORNER $\frac{36}{116} | \frac{31}{116}$ T 142 N R 546 W., WM.

HISTORICAL: GLO Pg. 7 L.N. 6 MARKED 15" CEDAR
SEE GLO. MICROFILM FOR CORNER
FOR USE OF O.S.B.F. 8-3-1874
BRASS CAP

CONDITION GOOD


FOUND 1 1/2" IRON PIPE WITH 3" O.S.B.F. BRASS CAP

GONE	ON WEST SIDE OF 15" CEDAR STUB 4' HIGH
GONE	8" HEMLOCK N. 17° E. 20 LKS G.L.O. Pg. 7
GONE	10" FIR N. 75° W. 43 LKS G.L.O. Pg. 7
GONE	7" CEDAR S. 45° W. 7 LKS G.L.O. Pg. 7
FD STUB 6" HIGH	12" FIR S. 50° E. 13 LKS G.L.O. Pg. 7
FACE GROWN OVER *	35" FIR S. 18° W 22' 40" NO RECORD O.S.B.F. PROBABLY
FACE GROWN OVER *	32" FIR S. 16° E 36' 50" NO RECORD " "

COMMENTS: RESCRIBED 35" & 32" FIR B.T CS DISTANCES TO NAIL WITH WASHER IN FACE.

REWITNESS

1 SET 10" CONCRETE CYLINDER AROUND FOUND O.S.B.F. 1 1/2" IRON PIPE WITH 3" BRASS CAP ON WEST SIDE OF 15" CEDAR STUB 4' HIGH. * 84" Hat Section NORTH 15 FEET



NEW ACCESSORY: DISTANCES TO NAIL WITH BRASS WASHER IN FACE

* 11" FIR	N. 73° E. 149'	T 2 N R 5 W S 31 B.T.C.

COMMENTS: THIS CORNER IS LOCATED ± 30' EAST OF A SMALL CREEK.

IN THE PRESENCE OF: DAN MCNUTT AL DVORAK

DATE: 6-88

PHOTO: [unclear]

* - County corner tag affixed.

TITLE