

TILLAMOOK COUNTY REWITNESS # 15

N.W. SEC. COR. 12 T 1N R 10 W., WM.

HISTORICAL: Book 10 Page 68 JAN. 1889

GLO Page 38 Book 3 Page 12

MAP B-4-19 MAP B-437

CORNER INFORMATION (RECORD IN GLO BOOK TINRIOW) IS IN ERROR AS COMPARED TO ACTUAL FIELD NOTES FOUND IN BOOK 10 PAGE 68. 75" Spruce S84W 19 IKS (GLO) IS ACTUALLY A 75" SPRUCE S34E 19 IKS (BK 10 P. 38).

CONDITION FAIR


FOUND: 1" Iron Pipe With Plug & Tack Book 3 Pg 12

Found <sup>STUMP</sup> Visible Scribing	75" Spr. S34°E 19 IKS = 12 <sup>54</sup> FT. Book 10 Page 68
STUMP WITH YELLOW TAG	24" Hem. N40°E 14 IKS = 9 <sup>24</sup> FT. Book 10 Page 68
Gene	12" Hem. N55°W 31 IKS = 20 <sup>46</sup> FT. Book 10 Page 68
STUMP WITH FACE	36" Spr. N76°W 31 <sup>5</sup> FT. Book 3 Page 12 SHEET ①
STUMP WITH FACE	30" Hem. S 2°E 24 <sup>8</sup> FT. Book 3 Page 12 SHEET ①
STUMP WITH FACE	36" Spr. S25°W 38 <sup>2</sup> FT. Book 3 Page 12 SHEET ①

COMMENTS: I FOUND CORNER ON RECENT NORTH-SOUTH CUTTING BY MAP B-419 SHOULD NOT BE MISTAKE FOR THE MORE RECENT P.P.L. Power Lines. P.P.L. POWER LINES ARE ± 1/4" TO WEST. P.U.D. POWER LINES ARE AT 320 WEST.

REWITNESS

I SET 2" IRON PIPE WITH A 3" BRASS CAP IN 10" TILE FILLED WITH CEMENT IN POSITION OF FOUND 1" IRON PIPE LAYING BESIDE MONUMENT " Hat Section



NEW ACCESSORY:


COMMENTS: CORNER IS LOCATED ± 150' SOUTH OF A CREEK RUNNING WEST AT THE EDGE OF OLD LOGGING AREA ± 400' WEST OF A LOGGING ROAD WHICH IS ON TOP OF A RIDGE.

IN THE PRESENCE OF: George W. Urrey  
W. Gale Arthur  
DAN MCNULTT

DATE: 5-74

PHOTO#: REC

County corner tag affixed.

TILLAMOOK COUNTY REWITNESS TITLE