

TILLAMOOK COUNTY REWITNESS # 25
 1/4 N. 8 SEC. 5
 COR. 8 T 1 N R 10 W., WM.

HISTORICAL: GLO 1N10 PAGE 48 1873


BOOK	PAGE	MAPS
OCEANLAKE PARK	A-2292	A-4133
SUBDIVISION FILE	B-1150	B-930
	B-815	
	F-40-139	THIS MAP IS DIFFERENT CORNER

CONDITION	FOUND:	CS "56" NAIL	SEE CS SUBDIVISION FILE	OCEANLAKE PARK
FD. ROTTEN STOB ^{BADLY DECAYED}	32" HEMLOCK	S. 40° W	38 LKS	GLO Pg. 48
FD. REMAINS OF UPROOT	30" HEMLOCK	N. 7° W	34 LKS	GLO Pg. 48
FOUND E-W BLAZED LINE	± 40 YEARS OLD	(ON LINE)		

COMMENTS:

REWITNESS

1 SET 1 1/2" IRON PIPE WITH 3" BRASS CAP IN CEMENT @
 POSITION USED BY CARLICH CS MAP# A-2292
 * 60" Hat Section EAST 15 FEET



NEW ACCESSORY: BTS ADDED 3-21-84

* 15" HEMLOCK	S. 80° W	35' ±	1/4 S 8° S B.T
* 10" HEMLOCK	N. 57° W	34' ±	1/4 S 5° S B.T
DISTANCES TO NAIL WITH BRASS WASHER IN FACE			

COMMENTS: THIS CORNER IS LOCATED ± 30' EAST ON A N-S CUTTING LINE. 1 1/2" IP SET BY PL THOMPSON CS MAP# F-40-139 BEARS N. 69° 28' 48" W 27' ±. CORNER FELL IN 24" HEMLOCK LOG ^{WAS} NOTCHED TO SET CORNER.

IN THE PRESENCE OF: ALLAN E. DUNCAN
 DAN McNUTT

DATE: DEC 1983

PHOTO#: 2807

County corner tag affixed.

TITLE