

15
22

TILLAMOOK COUNTY REWITNESS #36

N.22 SEC. 15
COR. 22 T 1N R 10 W., WM.
S.15

HISTORICAL: GLO Pg. 7 TINRIOW SET POST ± 1857

BOOK PAGE	MAPS	B-123
5 - 78	B-1206	B-289
FIELD NOTES C. BELL	A-102	
S22 TINRIOW	A-322	
	A-692	


CONDITION GOOD FOUND: 2" IRON PIPE PLUGGED & TACKED Bk 5 Pg 78

?	40" HEMLOCK	S45° W 7 LKS	GLO Pg. 7
GONE	12" HEMLOCK	N75° E 40 LKS	GLO Pg. 7
FOUND SCRIBING VISIBLE	34" HEMLOCK STUMP	S41° W 52 FT	FIELD NOTES

COMMENTS:

REWITNESS

I SET 2" IRON PIPE WITH 3" BRASS CAP IN 10" TILE AND CEMENT IN
POSITION OF FD 2" IRON PIPE PLUGGED & TACKED
84" Hat Section SOUTH 15 FEET



NEW ACCESSORY:

* 36" CROOKED HEMLOCK	N 79° W 63.43'	S15 BT CS
* 20" HEMLOCK	S 27° W 44.81'	1/4 S22 BT CS

COMMENTS: THIS CORNER IS LOCATED AT THE
SE EDGE OF A CLEARING ± 30' NORTH OF THE EDGE OF THE
TIMBER. I LAYED FD 2" IRON PIPE ALONGSIDE MONUMENT.

IN THE PRESENCE OF: GALE ARTHUR & DAN MENUTT

DATE: 3-23-76

COB*
W PHOTO# 260

* = County corner tag affixed.

TITLE