



TILLAMOOK COUNTY REWITNESS

#61

N.W. SEC. 35 T 10 N R 10 W., WM.  
COR. DLC.# 38

HISTORICAL: Book 5 Page 70

MAP A-1229

CONDITION

FOUND:

GOOD		2" Iron Pipe		A-1229 RS287
GOOD	OK 1973	* 24" Spruce	N49°W 765	Book 5 Page 70
GOOD	OK 1973	* 14" Spruce	S37°W 2440	Book 5 Page 70

COMMENTS: J.L. Carlich (RS287) - using information from maps A-307 and C-217 COUNTY SURVEYORS office - SET the 2" Iron Pipe in 1965.

REWITNESS

1 SET 2" Iron Pipe with 3" Brass Cap in 10" Tile filled with Conc. N. 15 feet

WEBBER  
DLC  
NW COR  
RS 287  
1973

72" Hat Section

NEW ACCESSORY:

COMMENTS: Corner falls 10' north of fence corner. fence proceeds east and south from fence corner.

-- CAP & TILE SET 1973 -- HAT SECTION FAIR 1973

IN THE PRESENCE OF:

GALE ARTHUR  
GEO. URREY

GALE ARTHUR  
DAN McNutt

DATE: 11-19-68

PHOTO#:

\* = County corner tag affixed.

TITLE