

3N10 36	3N9 31	TILLAMOOK COUNTY REWITNESS # 68 N.W. SEC. 6 T 2N R 9 W., WM. COR.
2N10 1	2N9 6	
Bk 4 P 94 YEAR 1952 HISTORICAL: Year 1872 Survey by C.J. HANDLEY Hem 16" N9°E 18.98 ft Hem 24" S70°E 3.30 ft Hem 8" S21°W 30.36 ft Hem 20" N38°W 59.40 ft		

Set 2" IP from which a
 Lead plug in lower step of
 concrete wall bears S8°W
 @ 53.78 ft, lead plug in
 concrete wall 2 feet from
 west end, bears N40°45'W
 @ 57.09 ft. A 36" Spruce
 bears S47°E 13.8 ft
 BY W.E. Anderson & F. Smith

WEANDERON tied to SE. Cor
 Section 36 3N10 See Map A746
 ALSO REFER to field notes filed
 in bin 3N10 Sec 36
 W.A. MARKHAM found original
 Government Corner in 1953
 MAP B-380 by J.L. CARLICH in 1950
 found 2" IP @ corner
 MAP B-387 by R. MORRIS found
 corner in 1958

CONDITION	FOUND:		
	1 1/2" Iron Pipe for Corner		
Partly Healed over	36" Spruce	S 42° E	13.80 ft
Δ on East side	Telephone (8" dia)	S 28° W	15.07 ft

COMMENTS: W.A. Markham was to township corner again in 1963 (see map A-1071)

REWITNESS

I SET

4 "x 4 "x 48" Post N. 10 feet

NEW ACCESSORY:

Power Pole # MO-C-7-L3	N 13° W	103.59

COMMENTS: Power Pole Δ on Eastside - Corner is at west edge of lawn at top of 6' high cut slope on east side of old county Road, (Tomlinson Rd)

IN THE PRESENCE OF: A.E. Duncan 793
 Gale Arthur

DATE: 3-27-67 PHOTO#: FCC-5-10-84

TITLE GWU

* - County corner tag affixed.