

TILLAMOOK COUNTY REWITNESS #69

T3NR10W 36	T3NR9W 31	N.W. 1/4 SEC. COR. 6 T 2N R 9 W., WM.
T2NR10W 1	T2NR9W 6	HISTORICAL: GLO T2NR9W Pages 3-4
		Book 4 Page 94
		MAP A-746      MAP A-1701
		MAP F-40-159
		MAP B-380
		MAP B-387

CONDITION GOOD FOUND: 1/2" Iron Pipe

Found Stone with 'X' lying by corner -- STONE WAS A 12" X 12" X 24" - Stone was placed in ditch near the County road.

ALL G.L.O. Bearing trees are gone.

Found lead plug set by Book 4 Page 94 at bearing & distance S3°W 53.78'

Found 36" Spruce set by Book 4 Page 94 at bearing & distance S47°E 132'

Lead plug by Bk 4 Page 94 at N40°45'W 57.09' is now missing.

COMMENTS:

REWITNESS

1 SET 2" Iron Pipe in Concrete and Tile with 3" Brass Cap

\* 4" x 4" x 48" Post N. NORTH feet 10

T3N

R10 | R9W

---

36 | 31

---

1 | 6

---

T2N

R5281

1972

NEW ACCESSORY:

Placed new yellow tag on 4x4 post

COMMENTS: Corner is located at the intersection of Nels Hanson County Road and the Miami-Foley county road.

IN THE PRESENCE OF: George W. Urrey Al Duncan  
Gale Arthur Tim Boehm  
Roger Knippel

DATE: 5-72

COB' PHOTO# REC

TILLAMOOK COUNTY REWITNESS TITLE

\* - County corner tag affixed.