

TILLAMOOK COUNTY REWITNESS # 70
 N. 2 COR. SEC. 35
 COR. 2 T2E3N R 10 W., WM.
 S. 35

HISTORICAL: GLO Pg. 18 2410 ± 1873

BOOK	PAGE	MAPS	A-3095
4	51	B-74	B-736
2	188	A-681	B-319
CT9	127	B-131	
4	24	B-380	

CONDITION	FOUND	3/4" I. P. PLUG & TACK	BK. 4 Pg. 51
NOT FOUND	6" HEMLOCK FOR CORNER		GLO Pg. 18
NOT FOUND	4" HEMLOCK	N. 70° W. 5 LKS	GLO Pg. 18
? SEE MAP B-736	30" HEMLOCK	S. 49° 45' W. 44'	BK. 4 Pg. 24
NOT FOUND	22" HEMLOCK	S. 17° 30' E. 87 3/4'	BK. 4 Pg. 24
FOUND GOOD	26" HEMLOCK	S. 40° E. 40'	BK. 4 Pg. 51
FOUND GOOD	7" HEMLOCK	N. 84° W. 28 1/2'	BK. 4 Pg. 51


COMMENTS: FD. 30" HEMLOCK STUMP POSSIBLY SAME AS 570' W 44' FACE CHOPPED OPEN ABOVE TREE WITH 44' DISTANCE

REWITNESS

OF FD 3/4" IRON PIPE

1 SET 2" IRON PIPE WITH 3" BRASS CAP IN 10" TILE & CEMENT @ POSITION

3"x 3"x 60" Post NLY. 2 3/4 FEET
 * 6-82 60" Hat Section NORTH. 1 1/2 FEET



NEW ACCESSORY:

6-82 60" FIR STUMP	S 81° W 17' 1/2 TO WALK
FD. I. P. LEANING & CEMENT BROKEN	6-82
STRAIGHTENED & RECEMENTED	

COMMENTS: THIS CORNER IS LOCATED ± 150' EAST OF A LOGGING ROAD ON THE WEST SLOPE OF A HILLSIDE.

IN THE PRESENCE OF: GALE ARTHUR DAN PENNITT

DATE: 12-28-78 PHOTO#:

12-28-78 [Signature]
 TITLE

* = County corner tag affixed.