

TILLAMOOK COUNTY REWITNESS

SEC.

INITIAL POINT 29 T 2 N R 10 W., WM. <sup>#91</sup> <sup>also 97</sup>

MANHATTAN

HISTORICAL: PLAT MAP C-15

	A-350
	A-392
	A-3808
	Book 7 Pg. 105

CONDITION

FOUND:


Found, good 1" Dia. IRON PIPE with a WOOD PLUG approx. 8" Below the road surface; WITH A 2" Dia. IRON PIPE (Boiler Tube) with a WOOD PLUG, driven down around the 1" I.P.; WITH A 1" Dia. BRASS DISK welded onto a 1/2" x 3" IRON ROD that was driven into the wood plug in the 2" I.P. The 2" I.P. and Brass Disk are approx. 6" Below the road surface.

COMMENTS:

There is also concrete around the 2" I.P.

REWITNESS

I SET A 3/4" x 15" IRON ROD with a BRASS CAP, inside the FOUND 1" I.P., that is inside the Found 2" I.P., now " Hat Section and I Filled the Hole with Concrete.



NEW ACCESSORY:

SE Cor. Garage	bears N 29 W	37 88 ft
NE Cor. House	" S 67 W	22 28 ft
SE Cor. House	" N 10 W	54 69 ft

COMMENTS: I Set the CS BC flash with the road surface. IT Falls approx. 3 ft West of the East edge of the road, and approx 3.5 ft West of the E of the SPRR.

IN THE PRESENCE OF:

TERRY JONES  
GALE ARTHUR

DATE: Oct. 1981

PHOTO# REC

\* - County corner tag affixed.

TITLE