


3 N. 10 W. 3 N. 17 W.

# 104

TILLAMOOK COUNTY REWITNESS



1/4 COR. SEC. 25+30T 3 N R 9+10W., WM.

HISTORICAL: C.S. MAP # B-675

BOOK	PAGE	MARS
6	170	B-675
1	218 DIFFERANT POSITION	

RESET BK 6 Pg 170


CONDITION GOOD FOUND, 3/4" I.P. WITH 3" CZ BRASS CAP B-675

DESTROYED BY LOGGING	12" D. FIR	S. 22° 45' E 32.76'	B-675
FD STUMP BOTTOM OF FACE WITH SCRIBING VISIBLE	13" D. FIR	S. 40° 58' W. 40.25'	B-675
FD. QK. = S. NE OF THE TOP OF A CUT FOR LOGGING	1/2" I.P. MARKERS	S. 53° 14' W. 55.10'	B-675
FD. GOOD SCRIBING VISIBLE	13" SPRUCE STUMP	S. 10° E. 22.03'	BK 6 Pg. 170

COMMENTS: THIS IS A PROPORTION CORNER NO ORIGINAL EVIDENCE WAS FOUND.

REWITNESS

1 SET 10" CONCRETE CYLINDER AROUND FOUND 3/4" IRON PIPE WITH 3" CZ BRASS CAP MAP B-675 (RESET 1981 BK. 6 Pg. 170) \* 72" Hat Section NORTH 15 FEET



NEW ACCESSORY:

NO NEW B.T.S	SET AS CORNER IS IN
A CLEAR CUT.	

COMMENTS: THIS CORNER IS LOCATED ± 75' NELY OF A GRAVEL LOGGING ROAD IN A RECENT CLEAR CUT.

IN THE PRESENCE OF: DAN MCNUTT AL DVORAK

DATE: 2-87

PHOTO#: 4-11-77

\* = County corner tag affixed.