

TILLAMOOK COUNTY REWITNESS #109

N.W. 11 SEC. 312  
 COR. 10/11 T 3N R 10 W., WM.  
 S. E. 3


HISTORICAL: GLO. Pg 23 ± 1873 GLO. Pg 50 & 51 ± 1893

MAPS
B-584
B-473

CONDITION	FOUND:	O. S. B. F.	BRASS CAP	MAP B-473
FD TO CEDAR STUMP FACE CHOPPED OUT DIST 19' 1/2"	40" CEDAR	N 13° W	28 LKS	GLO Pg 51
FD. ROTTEN STUMP DIST 33'	30" HEMLOCK	S 50° E	49 LKS	GLO Pg 51
NOT FOUND	28" HEMLOCK	S 20° W	70 LKS	GLO Pg 51
NOT FOUND	40" CEDAR	N 50° W	28 LKS	GLO Pg 23
FD. SNAG?	36" HEMLOCK	S 45° E	49 LKS	GLO Pg 23
NOT FOUND	36" HEMLOCK	S 31° W	70 LKS	GLO Pg 23
FOUND UNRECORDED B.T.'s	36" HEMLOCK	N 63° W	32.06'	CZTAG
COMMENTS:	36" HEMLOCK	N 46° E	12.24'	OSBFTAG
	30" HEMLOCK	S 89° E	31.35'	CZTAG

REWITNESS

I FOUND IRON PIPE WITH BRASS CAP (O.S.B.F.)  
 4" x 4" x 48" Post NORTH EAST 12 feet  
 Hat Section S. E.



NEW ACCESSORY:


COMMENTS: THIS CORNER IS LOCATED ON THE SOUTH SIDE OF A CREEK 1000 FT. EAST OF A LANDING.

IN THE PRESENCE OF: GALE ARTHUR & DAN McNUTT

DATE: 6-15-77 PHOTO# 2EC

\* - County corner tag affixed.

TILLAMOOK COUNTY CORNER TAG TITLE