

TILLAMOOK COUNTY REWITNESS # 114

N.W. 15th SEC. 9110
 COR. 16/15 T 3N R 10 W., WM.
 S. E. 9

HISTORICAL: GLO P930 ± 1873 & P953 ± 1893


BOOK	Pg.		
2	112		

CONDITION	ROTTEN	FOUND:	36" HEMLOCK STUMP	GLO P953
NOT FD.		40" FIR	N 20° E 20 LKS	GLO P930
NOT FD.		50" FIR	N 10° W 20 LKS	GLO P930
NOT FD.		24" HEMLOCK	S 45° E 30 LKS	GLO P9.30
FD. VERY ROTTEN		30" HEMLOCK	AT CORNER	GLO P953
NOT FD.		4" HEMLOCK	N 37° E 60 LKS	GLO P953
* FD. GOOD		8" HEMLOCK	N 87° W APP. 50'	BK 2 Pg. 112

COMMENTS: PLT 8" HEMLOCK BT BEARS N 89° W 54⁵⁰ FT. FROM MONUMENT

REWITNESS

I SET 2" IRON PIPE WITH 3" BRASS CAP IN 10" TILE & CEMENT
 IN CENTER OF STUMP & SAWED OUT.
 86" Hat Section EAST 12 FEET



NEW ACCESSORY:

	DISTANCES TO FACE	SCRIBED
* 10" HEMLOCK	S 26° E 26 ²³ FT.	S 15 BT CS
* 14" HEMLOCK	N 86° E 25 ⁰² FT.	S 10 BT CS
* 16" HEMLOCK	N 10° W 23 ⁰² FT.	S 9 BT CS

COMMENTS: FOUND P.L. THOMPSON 3/4" IRON PIPE WHICH
 BEARS N 68° W 2¹² FT FROM MONUMENT. CORNER IS LOCATED ± 55'
 SOUTH OF AN OLD ROAD GROWN OVER WITH ALDERS & ± 150' EAST OF
 A CREEK AT THE TOP OF A STEEP SLOPE WHICH DEPENDS SOUTH.

IN THE PRESENCE OF: GALE ARTHUR & DAN MCNUTT

DATE: 2-77 PHOTO#: TCC-5 7B-26

* = County corner tag affixed.

TITLE