

1514
2223

TILLAMOOK COUNTY REWITNESS

122

N.W. 23 SEC. 15/14
COR. 22/23 T 3N R 10 W., WM.
S. E. 15

HISTORICAL: GLO T3NR10W Pg 21 ± 1873


Book	PAGE
2	113

CONDITION	FOUND:		
FD. ROTTEN STUMP	126" SPRUCE	N 87° E	15 LKS GLO Pg. 21
GONE	4" V. MAPLE	S 13° W	23 LKS GLO Pg. 21
GONE	16" HEMLOCK	N 53° W	43 LKS GLO Pg. 21
FD. Now 40" STUMP SCRIBING READABLE	24" SPRUCE	N 37° W	21 FT BK. 2 Pg. 113
GONE	12" HEMLOCK	S 40° W	77 FT BK. 2 Pg. 113

COMMENTS:

REWITNESS

1 SET 2" IRON PIPE WITH 3" BRASS CAP IN 10" TILE & CEMENT
FROM FOUND P.L. THOMPSON B.T. BOOK 2 PAGE 113
84" Hat Section NORTH 12 FEET



NEW BEARING TREES	DISTANCES TO FACE	SCRIBED
40" SPRUCE	S15° E 62 ⁹³ FT	S23 BT CS
36" HEMLOCK	S64° W 36 ¹⁰ FT	S22 BT CS
20" HEMLOCK	N14° E 46 ¹⁸ FT	S15 BT CS
10" HEMLOCK	N34° W 29 ⁰⁶ FT	S14 BT CS

COMMENTS: THIS CORNER IS LOCATED ± 1100' EAST OF A LOGGING ROAD IN AN OLD CUTTING CORNER. A FENCE RUNS EAST FROM THE ORIGINAL 126" STUMP 10' EAST OF THE CORNER. ALSO ± 500' NORTH OF ANOTHER LOGGING ROAD

IN THE PRESENCE OF: GALE ARTHUR & DAN McNUYT

DATE: 2-77

PHOTO#: NWO-B 10-93

* = County corner tag affixed.

TITLE