

TILLAMOOK COUNTY REWITNESS

#125

SECTION COR. SEC. 18/17  
19/20 T 3N R 10 W., WM.

HISTORICAL: GLO T3NR10W Page 73

MAPS	Book	Page
A-28	3	17
F-4-G	1	492
C-171		
B-343		
B-340		


CONDITION FAIR FOUND: 1" HEXAGON STEEL ROD (Book 1 Page 492)

VISIBLE SCRIBING	5" X 5" X 36" POST		
* 7-18-94 FD. NOW 26" FACE NEAR	14" FIR	N 69° E 9.15 FT.	OTHER SIDE OF THIS CARD
* 7-18-94 FD NOW 40" FACE NEAR	40" O. FIR	N 76° W 66.95 FT.	" "
* NEW BT 7-18-94	10" FIR	S 31° W 10.84 FT.	SCRIBED 3N10 20 BT
* NEW BT 7-18-94	27" DOUBLE FIR	S 55° E 15.29 FT.	SCRIBED 3N10 19 BT

COMMENTS: DISTANCES TO NEW BTS, 7-18-94, WERE MEASURED TO A NAIL WITH BRASS WASHER AFFIXED OF THE BEARING TREE. BETWEEN THE B & T IN THE FACE

REWITNESS

1 SET 2" Iron PIPE WITH 3" Brass CAP in 10" Tile Filled with Conc. feet



\* 72" Hat Section North ~~FE~~ 25 FEET 7-18-94

NEW ACCESSORY:

* 14" Fir N 69 E	9.15	Has Do NOT cut Tag
* 40" Douglas Fir N 76 W	66.95	Has Do NOT cut Tag
Both BTS Have cor Tags.		

COMMENTS: Corner is in a mound of Rock on Steep Hillside ± 140<sup>00</sup> Feet North of U.S. Highway 101

Brass Cap was set in Place of found Hexagon Bar.

IN THE PRESENCE OF: Geo Urrey  
Gale Arthur  
Dan Msnutt

DATE: 10-73

PHOTO#: 16024 of J. Carlin  
C. Swanson

\* = County corner tag affixed.