

TILLAMOOK COUNTY REWITNESS

#143

W. 27 SEC. 28.27T 3N R 10 W., WM.  
COR. E. 28

HISTORICAL: GLO Page 26 (1873)

Book "53" Page 152 (1892)	MAP A-2015	MAP F-41-1
Map F-40-160 (1935)	MAP F-41-48	F-40-73
MAP F-20-1	MAP F-28-22	MAP A-376
Book "CT-9" Page 9	MAP A-376	
MAP A-479	MAP A-524	


CONDITION Fair FOUND: 1/4" Iron Pipe Refer. to F-40-160

GONE	13" Alder S70°W 60 <sup>1/4</sup> " = 39 <sup>5</sup> ft.	GLO (1873) Pg 26
GONE	16" Alder S18°E 29 <sup>1/4</sup> " = 19 <sup>1/4</sup> ft.	GLO (1873) Pg 26

COMMENTS:

REWITNESS

1 SET 2 1/2" with Brass Cap Iron Pipe with TWO 10" Tile and Conc around Cor.  
"x" "x" " Post N.W. feet



96 " Hat Section S. E. 23

NEW ACCESSORY:

*30" SPRUCE N67°W	30 <sup>1/4</sup>	SCRIBED	S28 BTCS
24" ALDER S4°W	20 <sup>30</sup>	" "	S28 BTCS

COMMENTS: Corner is south of HWY #101 AND ON THE EAST SIDE OF CREEK -- CORNER IS LOCATED IN NORTH-SOUTH FENCE. WE SET 2 1/2" IRON PIPE WITH 3" BRASSCAP OVER FOUND 1/4" IRON PIPE.

IN THE PRESENCE OF: Geo. W. Urrey  
Al E. Duncan  
Gale Arthur

DATE: June 1972 PHOTO#:

\* = County corner tag affixed.

TITLE