

TILLAMOOK COUNTY REWITNESS #249

N.W. 31 SEC. 25 30
COR. 36 31 T / S R 10 & 9 W., WM.
S. E. 25

HISTORICAL: ^{Pg. 79} GLO 159 ± 1857 SET POST

BOOK	PAGE	MAP	A-556
"H"	17, 21, 25	B-778	A-1726
4	78	A-2503	B-216
1	90	A-3220	B-105
4	44	A-935	


CONDITION GOOD FOUND: LEAD PLUG WITH TACK

FD. GOOD	LEAD PLUG IN CURB	N. 2° E. 58 ⁷ / ₂ FT	BK 4 Pg. 78
NOT FOUND	LEAD PLUG	S. 67° 49' E. 154 ²² / ₂	BK 4 Pg. 78
FD. GOOD	LEAD PLUG	S. 26° E. 105 ²³ / ₂	BK 4 Pg. 78
NOT FOUND	CAP TACK IN P4D P.P.	285 FT	BK 4 Pg. 78

COMMENTS:

REWITNESS

1 SET 1/2" IRON ROD WITH 3" BRASS CAP IN CONCRETE
ROAD @ POSITION OF FD. LEAD PLUG WITH TACK
" Hat Section S. E.



NEW ACCESSORY:

PP # X 37	S. 42° W. 98 ¹⁹ / ₂ FT	△
S. E. COR. BARN TAV. FD.	N. 39° W. 99 ³ / ₂ FT	

COMMENTS: THIS CORNER IS LOCATED IN THE CENTER OF THE NORTH BOUND LANE OF TILLAMOOK RIVER LOOP ROAD.

IN THE PRESENCE OF: DAN McNUTT GALE ARTHUR

DATE: 2-29-80

PHOTO#:

* = County corner tag affixed.

TITLE