

30	29
31	32

TILLAMOOK COUNTY REWITNESS #250

N.W. SEC. 32 T 15 R 9 W., WM.
COR.

HISTORICAL: GLO TISR9W ^{set Post} Page 64 1857

Book "H" Page 21	Set Spruce Post 1884	MAP F-7-19
Book "C+P" Page 88-89	WEA FLS 1952	MAP A-508 ^{WEA. 1952}
Book "S3" Page 4	1894	MAP B-601 ^{RS 287 1971}
MAP F-40-149	Fd Spruce limb ^{W. W. Hudson = 1950}	MAP A-2079 ^{RS 287 1971}
MAP A-593	Fd Spruce limb ^{S.L.C. RS 287 DEC 1984}	

Refer to Field notes in Sec 30 TISR9W

CONDITION

FOUND:

good:	1 1/2" Iron Pipe flush with ground
I REPLACED FOUND IRON PIPE WITH BRASS CAP	

COMMENTS: Fd a 1 1/2" unplugged Iron Pipe flush with the ground in the north-south fence line projection and Fd a spruce limb 0²⁰ west of 1 1/2" Iron pipe

REWITNESS

1 SET 2" Iron Pipe with Brass Cap in 6" Fite with Concrete
*96 HAT SECTION NORTH 140

TISR9W
30 | 29
31 | 32
RS287
1971

NEW ACCESSORY:

Power Pole # PP3800	N71°E	112.51	△
Power Pole # B17L4	N72°W	88.70	△
Guy Pole # B17L4	S84°W	80.78	

COMMENTS:


IN THE PRESENCE OF: AL DUNCAN
GALE ARTHUR
GEO. URREY

DATE: 1971

PHOTO#:

TITLE:

* = County corner tag affixed.



					(95)
30	29	159	STAN SKINNER		
31	32		± 1901		
Found old Spruce Limb 2' west of					
Fence Cor fences running S & E-W					
± 20' South of E of Maruff Loop					
Road					
Cor is The Fence Cor According To					
W.W. Hudson Map "D-144" sec 30/59					
For Pete Betshart Tracts					